

N/A

UCC3817ANG4

Tau Wae:

UCC3817ANG4


Kaihanga / Waitohu:

N/A

Whakaahuatanga hua

IC PFC CTRLR AVERAGE CURR 16DIP

Ngā Rauemi:

 Whakahaerehia te kore utu / RoHS

RoHS Tūnga

Hong Kong

Tuhinga mai i

DHL/Fedex/TNT/UPS/EMS

Te Ara Tuhi



No Picture

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o UCC3817ANG4

TAU WAE	UCC3817ANG4
KAIHANGA	N/A
WHAKAAHUATANGA	IC PFC CTRLR AVERAGE CURR 16DIP
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	12 V ~ 17 V
PŪRERE PŪRERE WHAKARATO	16-PDIP
RAUPAPA	-
PACKAGING	Tube
PAA / CASE	16-DIP (0.300", 7.62mm)
TAE MAHI	0°C ~ 70°C
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	2 (1 Year)
ARATAU	Average Current
TE TAE KAITUKU TAEKE	28 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
RAUTANGA - WHAKAWHITI	6kHz ~ 220kHz
WHAKAAHUATANGA TAIPITOPITO	PFC IC Average Current 6kHz ~ 220kHz 16-PDIP
ANEI - TE WHAKAOHO	150µA
TAU WAE TUAKIRI	UCC3817A

Ngā tūtohu e hāngai ana

UCC3817ANG4	Kaitoha UCC3817ANG4	Kaiwhakarato UCC3817ANG4
Utu UCC3817ANG4	Pikitia UCC3817ANG4	Whakaahua UCC3817ANG4
UCC3817ANG4 Pepa Raraunga PDF	UCC3817ANG4 Tango Whakahoki	Tapunga UCC3817ANG4
Hokona UCC3817ANG4	Hokona UCC3817ANG4	Hokona UCC3817ANG4
UCC3817ANG4	Kaiwhakarato	Kaitoha Kaatawhai

Ngā Hua e hāngai ana

 <p>UCC3817DG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 36664 pcs</p> <p>RFQ</p>	 <p>UCC3817APW Kaihanga: N/A Whakaahuatanga: IC PFC CTRL AVERAGE CURR 16TSSOP I roto i te taonga: 4776 pcs</p> <p>RFQ</p>
 <p>UCC3813PWTR-5G4 Kaihanga: N/A Whakaahuatanga: IC REG CTRLR MULT TOP 8TSSOP I roto i te taonga: 69288 pcs</p> <p>RFQ</p>	 <p>UCC3817ADR Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 70668 pcs</p> <p>RFQ</p>
 <p>UCC3817AN Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16DIP I roto i te taonga: 47946 pcs</p> <p>RFQ</p>	 <p>UCC3817APWG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRL AVERAGE CURR 16TSSOP I roto i te taonga: 4360 pcs</p> <p>RFQ</p>
 <p>UCC3817D Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 51983 pcs</p> <p>RFQ</p>	 <p>UCC3817AD Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 58044 pcs</p> <p>RFQ</p>
 <p>UCC3817APWR Kaihanga: N/A Whakaahuatanga: IC PFC CTRL AVERAGE CURR 16TSSOP I roto i te taonga: 4377 pcs</p> <p>RFQ</p>	 <p>UCC3817ADG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 44440 pcs</p> <p>RFQ</p>
 <p>UCC3813PWTR-5 Kaihanga: N/A Whakaahuatanga: IC REG CTRLR MULT TOP 8TSSOP I roto i te taonga: 83691 pcs</p> <p>RFQ</p>	 <p>UCC3817APWRG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRL AVERAGE CURR 16TSSOP I roto i te taonga: 5152 pcs</p> <p>RFQ</p>