

N/A

CDCV304PWRG4

Tau Wae: CDCV304PWRG4
 Kaihanga / Waitohu: N/A
 Whakaahuatanga hua: IC CLK BUFFER 1:4 200MHZ 8TSSOP
 Ngā Rauemi:
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS



TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o CDCV304PWRG4

TAU WAE	CDCV304PWRG4
KAIHANGA	N/A
WHAKAAHUATANGA	IC CLK BUFFER 1:4 200MHZ 8TSSOP
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	2.3 V ~ 3.6 V
MOMO	Fanout Buffer (Distribution)
PŪRERE PŪRERE WHAKARATO	8-TSSOP
RAUPAPA	-
RATONGA - WHAKAURU: WHAKAPUTA	1:4
PACKAGING	Tape & Reel (TR)
PAA / CASE	8-TSSOP (0.173", 4.40mm Width)
WHAKAPUTA	LVTTL
ĒTAHI INGOA	296-35899-2 CDCV304PWRG4-ND
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE TAE KAITUKU TAEKE	20 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAURU	LVTTL
TAUTANGA - MAX	200MHz
MOTUHAKA - WHAKAURU: WHAKAPUTA	No/No
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution) IC 1:4 200MHz 8-TSSOP (0.173", 4.40mm Width)
TAU WAE TUAKIRI	CDCV304

Ngā tūtohu e hāngai ana

CDCV304PWRG4	Kaitoha CDCV304PWRG4	Kaiwhakarato CDCV304PWRG4
Utu CDCV304PWRG4	Pikitia CDCV304PWRG4	Whakaahua CDCV304PWRG4
CDCV304PWRG4 Pepa Raraunga PDF	CDCV304PWRG4 Tango Whakahoki	Tapunga CDCV304PWRG4
Hokona CDCV304PWRG4	Hokona CDCV304PWRG4	Hokona CDCV304PWRG4
CDCV304PWRG4	Kaiwhakarato	Kaitoha Kaatawhai

Ngā Hua e hāngai ana

<p>CDCV850IDGG Kaihanga: N/A Whakaahuatanga: IC PLL CLOCK DRVR 2.5V 48-TSSOP I roto i te taonga: 23791 pcs</p> <p>RFQ</p>	<p>CDCUN1208LPEVM Kaihanga: N/A Whakaahuatanga: EVAL MODULE FOR CDCUN1208LP I roto i te taonga: 463 pcs</p> <p>RFQ</p>
<p>CDCV304PWR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:4 200MHZ 8TSSOP I roto i te taonga: 53713 pcs</p> <p>RFQ</p>	<p>CDCV304PWG4 Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:4 200MHZ 8TSSOP I roto i te taonga: 58720 pcs</p> <p>RFQ</p>
<p>CDCV850DGGG4 Kaihanga: N/A Whakaahuatanga: IC PLL CLOCK DRVR 2.5V 48TSSOP I roto i te taonga: 19469 pcs</p> <p>RFQ</p>	<p>CDCV304PW Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:4 200MHZ 8TSSOP I roto i te taonga: 55452 pcs</p> <p>RFQ</p>
<p>CDCUN1208LPRHBT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:8 400MHZ 32QFN I roto i te taonga: 15468 pcs</p> <p>RFQ</p>	<p>CDCV850DGGRG4 Kaihanga: N/A Whakaahuatanga: IC PLL CLOCK DRVR 2.5V 48TSSOP I roto i te taonga: 27994 pcs</p> <p>RFQ</p>
<p>CDCV304TPWREP Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:4 200MHZ 8TSSOP I roto i te taonga: 21714 pcs</p> <p>RFQ</p>	<p>CDCV850DGG Kaihanga: N/A Whakaahuatanga: IC PLL CLOCK DRVR 2.5V 48-TSSOP I roto i te taonga: 22414 pcs</p> <p>RFQ</p>
<p>CDCV850DGGR Kaihanga: N/A Whakaahuatanga: IC PLL CLOCK DRVR 2.5V 48-TSSOP I roto i te taonga: 26517 pcs</p> <p>RFQ</p>	<p>CDCUN1208LPRHBR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:8 400MHZ 32QFN I roto i te taonga: 15812 pcs</p> <p>RFQ</p>