

N/A

CDCL1810RGZRG4

Tau Wae: CDCL1810RGZRG4
 Kaihanga / Waitohu: N/A
 Whakaahuatanga hua: IC CLK BUFFER 1:10 650MHZ 48VQFN
 Ngā Rauemi:
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS



TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o CDCL1810RGZRG4

TAU WAE	CDCL1810RGZRG4
KAIHANGA	N/A
WHAKAAHUATANGA	IC CLK BUFFER 1:10 650MHZ 48VQFN
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	1.7 V ~ 1.9 V
MOMO	Fanout Buffer (Distribution), Divider
PŪRERE PŪRERE WHAKARATO	48-VQFN (7x7)
RAUPAPA	-
RATONGA - WHAKAURU: WHAKAPUTA	1:10
PACKAGING	Tape & Reel (TR)
PAA / CASE	48-VFQFN Exposed Pad
WHAKAPUTA	CML
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
TE TAE KAITUKU TAEKE	20 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAURU	LVDS
TAUTANGA - MAX	650MHz
MOTUHAKE - WHAKAURU: WHAKAPUTA	Yes/Yes
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution), Divider IC 1:10 650MHz 48-VFQFN Exposed Pad
TAU WAE TUAKIRI	CDCL1810

Ngā tūtohu e hāngai ana

CDCL1810RGZRG4	Kaitoha CDCL1810RGZRG4	Kaiwhakarato CDCL1810RGZRG4
Utu CDCL1810RGZRG4	Pikitia CDCL1810RGZRG4	Whakaahua CDCL1810RGZRG4
CDCL1810RGZRG4 Pepa Raraunga PDF	CDCL1810RGZRG4 Tango Whakahoki	Tapunga CDCL1810RGZRG4
Hokona CDCL1810RGZRG4	Hokona CDCL1810RGZRG4	Hokona CDCL1810RGZRG4
CDCL1810RGZRG4	Kaiwhakarato	Kaitoha Kaatawhai

Ngā Hua e hāngai ana

<p>CDCL6010RGZRG4 Kaihanga: N/A Whakaahuatanga: IC CLOCK MULT 1.8V 11OUT 48-QFN I roto i te taonga: 10375 pcs</p> <p>RFQ</p>	<p>CDCL6010RGZTG4 Kaihanga: N/A Whakaahuatanga: IC CLOCK MULT 1.8V 11OUT 48-QFN I roto i te taonga: 8096 pcs</p> <p>RFQ</p>
<p>CDCL6010RGZR Kaihanga: N/A Whakaahuatanga: IC CLOCK MULT 1.8V 11OUT 48-QFN I roto i te taonga: 9504 pcs</p> <p>RFQ</p>	<p>CDCI6214RGET Kaihanga: N/A Whakaahuatanga: LOW POWER CLOCK GENERATOR FOR IN I roto i te taonga: 25607 pcs</p> <p>RFQ</p>
<p>CDCL1810ARGZT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:10 650MHZ 48VQFN I roto i te taonga: 10271 pcs</p> <p>RFQ</p>	<p>CDCL6010RGZT Kaihanga: N/A Whakaahuatanga: IC CLOCK MULT 1.8V 11OUT 48-VQFN I roto i te taonga: 7495 pcs</p> <p>RFQ</p>
<p>CDCL1810RGZT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:10 650MHZ 48VQFN I roto i te taonga: 9304 pcs</p> <p>RFQ</p>	<p>CDCL1810RGZR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:10 650MHZ 48VQFN I roto i te taonga: 12636 pcs</p> <p>RFQ</p>
<p>CDCI6214EVM Kaihanga: N/A Whakaahuatanga: CDCI6214EVM I roto i te taonga: 556 pcs</p> <p>RFQ</p>	<p>CDCL1810RGZTG4 Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:10 650MHZ 48VQFN I roto i te taonga: 8417 pcs</p> <p>RFQ</p>
<p>CDCL1810ARGZR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:10 650MHZ 48VQFN I roto i te taonga: 12212 pcs</p> <p>RFQ</p>	<p>CDCI6214RGER Kaihanga: N/A Whakaahuatanga: CDCI6214RGER I roto i te taonga: 36636 pcs</p> <p>RFQ</p>