


N/A

## LMK04011BISQ/NOPB

Tau Wae: LMK04011BISQ/NOPB  
 Kaihanga / Waitohu: N/A  
 Whakaahuatanga hua: IC CLOCK COND W/PLL 48WQFN  
 Ngā Rauemi:  
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS  
 Tuhinga mai i: Hong Kong  
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS



**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o LMK04011BISQ/NOPB

TAU WAE	LMK04011BISQ/NOPB
KAIHANGA	N/A
WHAKAAHUATANGA	IC CLOCK COND W/PLL 48WQFN
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	3.15 V ~ 3.45 V
MOMO	Clock Conditioner
PŪRERE PŪRERE WHAKARATO	48-WQFN (7x7)
RAUPAPA	-
RATONGA - WHAKAURU: WHAKAPUTA	2:5
PACKAGING	Tape & Reel (TR)
PAA / CASE	48-WFQFN Exposed Pad
PLL	Yes
WHAKAPUTA	2VPECL, LVPECL
ĒTAHI INGOA	LMK04011BISQ LMK04011BISQ-ND
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
TE TAE KAITUKU TAEKE	26 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAURU	LVC MOS, LVDS, LVPECL
TAUTANGA - MAX	1.57GHz
KAWEWEHE / WHAKANAO	Yes/Yes
MOTUHAKA - WHAKAURU: WHAKAPUTA	Yes/Yes
TAU WAE TUAKIRI	LMK04011

### Ngā tūtohu e hāngai ana

LMK04011BISQ/NOPB	Kaitoha LMK04011BISQ/NOPB	Kaiwhakarato LMK04011BISQ/NOPB
Utu LMK04011BISQ/NOPB	Pikitia LMK04011BISQ/NOPB	Whakaahua LMK04011BISQ/NOPB
LMK04011BISQ/NOPB Pepa Raraunga PDF	LMK04011BISQ/NOPB Tango Whakahoki	Tapunga LMK04011BISQ/NOPB
Hokona LMK04011BISQ/NOPB	Hokona LMK04011BISQ/NOPB	Hokona LMK04011BISQ/NOPB
LMK04011BISQ/NOPB	Kaiwhakarato	Kaitoha Kaatawhai

### Ngā Hua e hāngai ana

<p><b>LMK04031BEVAL/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: EVAL BOARD LMK04031BISQ                  I roto i te taonga: 337 pcs  <a href="#">RFQ</a></p>	<p><b>LMK04011BISQX/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLOCK COND W/PLL 48WQFN                  I roto i te taonga: 7598 pcs  <a href="#">RFQ</a></p>
<p><b>LMK04010BISQ/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLOCK COND W/PLL 48WQFN                  I roto i te taonga: 6904 pcs  <a href="#">RFQ</a></p>	<p><b>LMK04002BISQE/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLOCK COND 1.6GHZ W/PLL 48QFN                  I roto i te taonga: 5843 pcs  <a href="#">RFQ</a></p>
<p><b>LMK04002BISQ/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLOCK COND W/PLL 48WQFN                  I roto i te taonga: 7413 pcs  <a href="#">RFQ</a></p>	<p><b>LMK04002BISQX/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLOCK COND W/PLL 48WQFN                  I roto i te taonga: 7620 pcs  <a href="#">RFQ</a></p>
<p><b>LMK04010BISQX/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLOCK COND W/PLL 48WQFN                  I roto i te taonga: 6887 pcs  <a href="#">RFQ</a></p>	<p><b>LMK04031BISQE/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLOCK COND W/PLL 48WQFN                  I roto i te taonga: 5220 pcs  <a href="#">RFQ</a></p>
<p><b>LMK04031BEVALXO</b>                  Kaihanga: N/A                  Whakaahuatanga: BOARD EVAL PREC CLOCK PLL XO                  I roto i te taonga: 5095 pcs  <a href="#">RFQ</a></p>	<p><b>LMK04011BISQE/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLOCK COND W/PLL 48WQFN                  I roto i te taonga: 5033 pcs  <a href="#">RFQ</a></p>
<p><b>LMK04031BISQ/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLOCK COND W/PLL 48WQFN                  I roto i te taonga: 7600 pcs  <a href="#">RFQ</a></p>	<p><b>LMK04010BISQE/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLOCK COND 1.2GHZ W/PLL 48QFN                  I roto i te taonga: 5465 pcs  <a href="#">RFQ</a></p>