



TDK Corporation

HHM1715E1

Tau Wae:

HHM1715E1

Kaihanga / Waitohu:

TDK Corporation


Whakaahuatanga hua

BALUN 3.3GHZ-3.9GHZ 50/100 0603

Ngā Rauemi:

 HHM1715E1.pdf

RoHS Tūnga

 Whakahaerehia te kore utu / RoHS

Tuhinga mai i

Hong Kong


Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o HHM1715E1

TAU WAE	HHM1715E1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 3.3GHZ-3.9GHZ 50/100 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	 HHM1715E1.pdf
RAUPAPA	HHM
HOKI HOKI (MIN)	10dB
RAWEHANGA PUTANGA	180° ±15°
PACKAGING	Cut Tape (CT)
PAA / CASE	0603 (1608 Metric)
ĒTAHI INGOA	445-3995-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE TAE KAITUKU TAEKE	12 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	1.0dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 100 Ohm
MAHINGA RAWE	3.3GHz ~ 3.9GHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 3.3GHz ~ 3.9GHz 50 / 100 Ohm 0603 (1608 Metric)

Ngā tūtohu e hāngai ana

TDK Corporation HHM1715E1	Kaitoha HHM1715E1	Kaiwhakarato HHM1715E1
Utu HHM1715E1	Pikitia HHM1715E1	Whakaahua HHM1715E1
HHM1715E1 Pepa Raraunga PDF	HHM1715E1 Tango Whakahoki	Tapunga HHM1715E1
Hokona HHM1715E1	Hokona HHM1715E1	Hokona TDK Corporation HHM1715E1
TDK Corporation HHM1715E1	Kaiwhakarato TDK Corporation	Kaitoha Kaatawhai TDK Corporation
TDK Corporation HHM1715E1		

Ngā Hua e hāngai ana

 <p>HHM1727D1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.3GHZ-3.9GHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM17165A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.8GHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>HHM17166A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.9GHZ-2.3GHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM17153A2 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 698MHZ-894MHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>HHM17168B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.4GHZ-3.8GHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM17144A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 791MHZ-960MHZ 50/100 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>HHM17146A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.92GHZ-2.17GHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM17139B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>HHM17152A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 698MHZ-894MHZ 50/100 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM1726N1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-915MHZ 50/100 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>HHM1726P1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 880MHZ-960MHZ 50/100 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM17139B2 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.6GHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>