



Pulse Electronics Corporation

TM1062FUB

Tau Wae:	TM1062FUB
Kaihanga / Waitohu:	Pulse Electronics Corporation
Whakaahuatanga hua:	TRANSCEIVER MODULE PBC
Ngā Rauemi:	1.TM1062FUB.pdf 2.TM1062FUB.pdf
RoHS Tūnga	Tonohia te taunakitanga tuhinga / RoHS kaore i te ture
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o TM1062FUB

TAU WAE	TM1062FUB
KAIHANGA	Pulse Electronics Corporation
WHAKAAHUATANGA	TRANSCEIVER MODULE PBC
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Tonohia te taunakitanga tuhinga / RoHS kaore i te ture
PEPA RARAUNGA	1.TM1062FUB.pdf 2.TM1062FUB.pdf
TUHINGA O MUA	3.3V
MOMO	Transceiver
PŪRERE PŪRERE WHAKARATO	Module
RAUPAPA	Copperhead™
TUHINGA	IEEE 1394B
PAA / CASE	28-SMD Module
TAE MAHI	-55°C ~ 125°C
TE MAHA O NGA KAIKOI / KAIWHIWHI	1/1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
TE TAE KAITUKU TAEKE	19 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Request inventory verification / RoHS non-compliant
POROHITA	-
WHAKAAHUATANGA TAIPITOPITO	1/1 Transceiver IEEE 1394B Module
RARAUNGA RARAUNGA	1.062Gbps

Ngā tūtohu e hāngai ana

Pulse Electronics Corporation TM1062FUB	Kaitoha TM1062FUB	Kaiwhakarato TM1062FUB
Utu TM1062FUB	Pikitia TM1062FUB	Whakaahua TM1062FUB
TM1062FUB Pepa Raraunga PDF	TM1062FUB Tango Whakahoki	Tapunga TM1062FUB
Hokona TM1062FUB	Hokona TM1062FUB	Hokona Pulse Electronics Corporation TM1062FUB
Pulse Electronics Corporation TM1062FUB	Kaiwhakarato Pulse Electronics Corporation	Kaitoha Kaatawhai Pulse Electronics Corporation
Pulse Electronics Corporation TM1062FUB	Pulse A Technitrol Company TM1062FUB	Pulse TM1062FUB

Ngā Hua e hāngai ana

<p>TM1062FCA1 Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER PBC I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>TM1062HUXB Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER MODULE IEEE1394B I roto i te taonga: 9 pcs</p> <p>RFQ</p>
<p>TM1062DVB2 Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER PBC I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>TM1062FSB2 Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER MODULE PBC I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>TM1062HUB5 Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER TM1062HUB5 PBC I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>TM1062FCA2 Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER PBC I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>TM1062HSB1 Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER TM1062HSB1 PBC I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>TM1062FSB Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER MODULE PBC I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>TM1062HSCT Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER PBC I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>TM1062HUCT Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER PBC I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>TM1062FSA Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER PBC I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>TM1062HUXBT Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER TM1062HUXB PBC I roto i te taonga: Out stock</p> <p>RFQ</p>

