



TDK Corporation

## HHM1589E1

Tau Wae:

HHM1589E1

Kaihanga / Waitohu:

TDK Corporation


Whakaahuatanga hua

BALUN 350MHZ-470MHZ 50/200 0805

Ngā Rauemi:

 HHM1589E1.pdf

RoHS Tūnga

 Whakahaerehia te kore utu / RoHS

Tuhinga mai i

Hong Kong

Te Ara Tuhi


DHL/Fedex/TNT/UPS/EMS



### TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













### Ngā whakaaturanga o HHM1589E1

TAU WAE	HHM1589E1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 350MHZ-470MHZ 50/200 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	 HHM1589E1.pdf
RAUPAPA	*
PACKAGING	Cut Tape (CT)
PAA / CASE	0805 (2012 Metric), 6 PC Pad
ĒTAHI INGOA	445-175631-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE TAE KAITUKU TAEKE	12 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	RF Balun 0805 (2012 Metric), 6 PC Pad

### Ngā tūtohu e hāngai ana

TDK Corporation HHM1589E1	Kaitoha HHM1589E1	Kaiwhakarato HHM1589E1
Utu HHM1589E1	Pikitia HHM1589E1	Whakaahua HHM1589E1
HHM1589E1 Pepa Raraunga PDF	HHM1589E1 Tango Whakahoki	Tapunga HHM1589E1
Hokona HHM1589E1	Hokona HHM1589E1	Hokona TDK Corporation HHM1589E1
TDK Corporation HHM1589E1	Kaiwhakarato TDK Corporation	Kaitoha Kaatawhai TDK Corporation
TDK Corporation HHM1589E1		

### Ngā Hua e hāngai ana

 <p><b>HHM1603A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.7GHZ 50/100 4SMD I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>HHM1570B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>HHM1564A4</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-894MHZ 50/200 0805 I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>HHM1562B</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 5.15-5.875GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>HHM1583B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.1GHZ-4.9GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>HHM1591D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 350MHZ-470MHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>HHM1548E1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.2GHZ-3.9GHZ 50/200 0805 I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>HHM1710D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>HHM1711D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0603 I roto i te taonga: 503 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>HHM1589B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 470MHZ-710MHZ 6SMD I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>HHM1595A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3GHZ-8GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>HHM1596A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.1GHZ-4.9GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>

