

N/A

UCC3819D

Tau Wae: UCC3819D
 Kaihanga / Waitohu: N/A
 Whakaahuatanga hua: IC PFC CTRLR AVERAGE CURR 16SOIC
 Ngā Rauemi:
 RoHs Tūnga: Whakahaerehia te kore utu / RoHS
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS



TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o UCC3819D

TAU WAE	UCC3819D
KAIHANGA	N/A
WHAKAAHUATANGA	IC PFC CTRLR AVERAGE CURR 16SOIC
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	10.8 V ~ 17 V
PŪRERE PŪRERE WHAKARATO	16-SOIC
RAUPAPA	-
PACKAGING	Tube
PAA / CASE	16-SOIC (0.154", 3.90mm Width)
TAE MAHI	0°C ~ 70°C
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	2 (1 Year)
ARATAU	Average Current
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
RAUTANGA - WHAKAWHITI	250kHz
WHAKAAHUATANGA TAIPITOPITO	PFC IC Average Current 250kHz 16-SOIC
ANEI - TE WHAKAOHO	150µA
TAU WAE TUAKIRI	UCC3819

Ngā tūtohu e hāngai ana

UCC3819D	Kaitoha UCC3819D	Kaiwhakarato UCC3819D
Utu UCC3819D	Pikitia UCC3819D	Whakaahua UCC3819D
UCC3819D Pepa Raraunga PDF	UCC3819D Tango Whakahoki	Tapunga UCC3819D
Hokona UCC3819D	Hokona UCC3819D	Hokona UCC3819D
UCC3819D	Kaiwhakarato	Kaitoha Kaatawhai

Ngā Hua e hāngai ana

<p>UCC381DP-3 Kaihanga: N/A Whakaahuatanga: IC REG LINEAR 3.3V 1A 8SOIC I roto i te taonga: 33160 pcs</p> <p>RFQ</p>	<p>UCC381DP-5G4 Kaihanga: N/A Whakaahuatanga: IC REG LINEAR 5V 1A 8SOIC I roto i te taonga: 23841 pcs</p> <p>RFQ</p>
<p>UCC3819APWR Kaihanga: N/A Whakaahuatanga: IC PFC CTRL AVERAGE CURR 16TSSOP I roto i te taonga: 4160 pcs</p> <p>RFQ</p>	<p>UCC3819N Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16DIP I roto i te taonga: 4408 pcs</p> <p>RFQ</p>
<p>UCC381DP-ADJ Kaihanga: N/A Whakaahuatanga: IC REG LINEAR POS ADJ 1A 8SOIC I roto i te taonga: 31088 pcs</p> <p>RFQ</p>	<p>UCC381DP-5 Kaihanga: N/A Whakaahuatanga: IC REG LINEAR 5V 1A 8SOIC I roto i te taonga: 31619 pcs</p> <p>RFQ</p>
<p>UCC3819APWRG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRL AVERAGE CURR 16TSSOP I roto i te taonga: 4528 pcs</p> <p>RFQ</p>	<p>UCC3819AN Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16DIP I roto i te taonga: 4840 pcs</p> <p>RFQ</p>
<p>UCC3819DG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 4467 pcs</p> <p>RFQ</p>	<p>UCC3819ANG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16DIP I roto i te taonga: 4007 pcs</p> <p>RFQ</p>
<p>UCC3819APW Kaihanga: N/A Whakaahuatanga: IC PFC CTRL AVERAGE CURR 16TSSOP I roto i te taonga: 4429 pcs</p> <p>RFQ</p>	<p>UCC3819APWG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRL AVERAGE CURR 16TSSOP I roto i te taonga: 5930 pcs</p> <p>RFQ</p>