



Intersil

X5648S14I

Tau Wae:

X5648S14I

Kaihanga / Waitohu:

Intersil

Whakaahuatanga hua

IC SUPERVISOR CPU 64K EE 14-SOIC

Ngā Rauemi:

 X5648S14I.pdf

RoHS Tūnga

 Kei roto nga rangatira / RoHS kaore i te ture

Tuhinga mai i

Hong Kong


Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS



Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o X5648S14I

TAU WAE	X5648S14I
KAIHANGA	Intersil
WHAKAAHUATANGA	IC SUPERVISOR CPU 64K EE 14-SOIC
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
PEPA RARAUNGA	 X5648S14I.pdf
PUTANGA - TAE	4.38V
MOMO	Simple Reset/Power-On Reset
PŪRERE PŪRERE WHAKARATO	14-SOIC
RAUPAPA	-
TAUTUHI TAUTUHI	100 ms Minimum
TAUTUHI ANŌ	Active Low
PACKAGING	Tube
PAA / CASE	14-SOIC (0.154", 3.90mm Width)
WHAKAPUTA	Open Drain or Open Collector
TAE MAHI	-40°C ~ 85°C (TA)
TE MAHA O NGA TAUMAHA AROTURUKI	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAAHUATANGA TAIPITOPITO	Supervisor Open Drain or Open Collector 1 Channel 14-SOIC
TAU WAE TUAKIRI	X5648

Ngā tūtohu e hāngai ana

Intersil X5648S14I	Kaitoha X5648S14I	Kaiwhakarato X5648S14I
Utu X5648S14I	Pikitia X5648S14I	Whakaahua X5648S14I
X5648S14I Pepa Raraunga PDF	X5648S14I Tango Whakahoki	Tapunga X5648S14I
Hokona X5648S14I	Hokona X5648S14I	Hokona Intersil X5648S14I
Intersil X5648S14I	Kaiwhakarato Intersil	Kaitoha Kaatawhai Intersil
Intersil X5648S14I		

Ngā Hua e hāngai ana

 <p>X5648S14-2.7T1 Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 14-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>X5648PI-4.5A Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 8-DIP I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>X5648S14I-4.5A Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 14-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>X5648S14-2.7 Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 14-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>X5648S14-2.7A Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 14-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>X5648S14I-2.7A Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 14-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>X5648S14T1 Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 14-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>X5648S14 Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 14-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>X5648S14IT1 Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 14-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>X5648S14I-2.7 Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 14-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>X5648S14-4.5A Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 14-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>X5648S14I-2.7T1 Kaihanga: Intersil Whakaahuatanga: IC SUPERVISOR CPU 64K EE 14-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>

Manaakitanga © 2020 Kaihoko Motuhake o nga Huinga Tiko - Ocean-Components.com

Ī-mēra: Info@Ocean-Components.com

Wāhi noho: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

