

N/A

TPS3847085DBVT

Tau Wae:	TPS3847085DBVT
Kaihanga / Waitohu:	N/A
Whakaahuatanga hua	IC VOLTAGE SUPERVISOR 5SOT23
Ngā Rauemi:	
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS



TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o TPS3847085DBVT

TAU WAE	TPS3847085DBVT
KAIHANGA	N/A
WHAKAAHUATANGA	IC VOLTAGE SUPERVISOR 5SOT23
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
PUTANGA - TAE	8.5V
MOMO	Simple Reset/Power-On Reset
PŪRERE PŪRERE WHAKARATO	SOT-23-5
RAUPAPA	-
TAUTUHI TAUTUHI	4.5 ms Typical
TAUTUHI ANŌ	Active Low
PACKAGING	Original-Reel®
PAA / CASE	SC-74A, SOT-753
WHAKAPUTA	Push-Pull, Totem Pole
ĒTAHI INGOA	296-38347-6
TAE MAHI	-40°C ~ 85°C (TJ)
TE MAHA O NGA TAUMAHA AROTURUKI	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	2 (1 Year)
TE TAE KAITUKU TAEKE	8 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	Supervisor Push-Pull, Totem Pole 1 Channel SOT-23-5

Ngā tūtohu e hāngai ana

TPS3847085DBVT	Kaitoha TPS3847085DBVT	Kaiwhakarato TPS3847085DBVT
Utu TPS3847085DBVT	Pikitia TPS3847085DBVT	Whakaahua TPS3847085DBVT
TPS3847085DBVT Pepa Raraunga PDF	TPS3847085DBVT Tango Whakahoki	Tapunga TPS3847085DBVT
Hokona TPS3847085DBVT	Hokona TPS3847085DBVT	Hokona TPS3847085DBVT
TPS3847085DBVT	Kaiwhakarato	Kaitoha Kaatawhai

Ngā Hua e hāngai ana

<p>TPS3847085DBVR Kaihanga: N/A Whakaahuatanga: IC VOLTAGE SUPERVISOR 5SOT23 I roto i te taonga: 92199 pcs</p> <p>RFQ</p>	<p>TPS3850G09QDRCRQ1 Kaihanga: N/A Whakaahuatanga: VOLTAGE SUPERVISOR WITH WATCHDOG I roto i te taonga: 89343 pcs</p> <p>RFQ</p>
<p>TPS3839K50DQNT Kaihanga: N/A Whakaahuatanga: IC LP SUPERVISORY CIRCUIT 4X2SON I roto i te taonga: 168474 pcs</p> <p>RFQ</p>	<p>TPS3839L30DBZT Kaihanga: N/A Whakaahuatanga: IC LP SUPERVISORY CIRCUIT SOT23-3 I roto i te taonga: 170928 pcs</p> <p>RFQ</p>
<p>TPS3847108DBVR Kaihanga: N/A Whakaahuatanga: IC VOLT MONITOR 10.8V SOT23-5 I roto i te taonga: 100791 pcs</p> <p>RFQ</p>	<p>TPS3850G12DRCR Kaihanga: N/A Whakaahuatanga: PRECISION VOLTAGE SUPERVISOR WIT I roto i te taonga: 72251 pcs</p> <p>RFQ</p>
<p>TPS3839L30DBZR Kaihanga: N/A Whakaahuatanga: IC LP SUPERVISORY CIRCUIT SOT23-3 I roto i te taonga: 270952 pcs</p> <p>RFQ</p>	<p>TPS3847085EVM-577 Kaihanga: N/A Whakaahuatanga: EVAL BOARD FOR TPS3847085 I roto i te taonga: 5354 pcs</p> <p>RFQ</p>
<p>TPS3850EVM-781 Kaihanga: N/A Whakaahuatanga: EVAL BOARD FOR TPS3850 I roto i te taonga: 3083 pcs</p> <p>RFQ</p>	<p>TPS3847108DBVT Kaihanga: N/A Whakaahuatanga: SUPERVISORY CIRCUITS I roto i te taonga: 63718 pcs</p> <p>RFQ</p>
<p>TPS3839L30DQNT Kaihanga: N/A Whakaahuatanga: IC LP SUPERVISORY CIRCUIT 4X2SON I roto i te taonga: 182559 pcs</p> <p>RFQ</p>	<p>TPS3839L30DQNR Kaihanga: N/A Whakaahuatanga: IC LP SUPERVISORY CIRCUIT 4X2SON I roto i te taonga: 180806 pcs</p> <p>RFQ</p>