



Pulse Electronics Corporation

TM1062HSB1

Tau Wae:	TM1062HSB1
Kaihanga / Waitohu:	Pulse Electronics Corporation
Whakaahuatanga hua:	TRANSCEIVER TM1062HSB1 PBC
Ngā Rauemi:	1.TM1062HSB1.pdf 2.TM1062HSB1.pdf
RoHS Tūnga	Tonohia te taunakitanga tuhinga / RoHS kaore i te ture
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o TM1062HSB1

TAU WAE	TM1062HSB1
KAIHANGA	Pulse Electronics Corporation
WHAKAAHUATANGA	TRANSCEIVER TM1062HSB1 PBC
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Tonohia te taunakitanga tuhinga / RoHS kaore i te ture
PEPA RARAUNGA	1.TM1062HSB1.pdf 2.TM1062HSB1.pdf
TUHINGA O MUA	3.3V
MOMO	Transceiver
PŪRERE PŪRERE WHAKARATO	Module
RAUPAPA	Copperhead™
TUHINGA	IEEE 1394B
PAA / CASE	16-SMD Module
TAE MAHI	-55°C ~ 125°C
TE MAHA O NGA KAIKOI / KAIWHIWHI	1/1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
TE TAE KAITUKU TAEKE	19 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Request inventory verification / RoHS non-compliant
POROHITA	-
WHAKAAHUATANGA TAIPITOPITO	1/1 Transceiver IEEE 1394B Module
RARAUNGA RARAUNGA	1.062Gbps

Ngā tūtohu e hāngai ana

Pulse Electronics Corporation TM1062HSB1	Kaitoha TM1062HSB1	Kaiwhakarato TM1062HSB1
Utu TM1062HSB1	Pikitia TM1062HSB1	Whakaahua TM1062HSB1
TM1062HSB1 Pepa Raraunga PDF	TM1062HSB1 Tango Whakahoki	Tapunga TM1062HSB1
Hokona TM1062HSB1	Hokona TM1062HSB1	Hokona Pulse Electronics Corporation TM1062HSB1
Pulse Electronics Corporation TM1062HSB1	Kaiwhakarato Pulse Electronics Corporation	Kaitoha Kaatawhai Pulse Electronics Corporation
Pulse Electronics Corporation TM1062HSB1	Pulse A Technitrol Company TM1062HSB1	Pulse TM1062HSB1

Ngā Hua e hāngai ana

<p>TM1062FSB2 Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER MODULE PBC I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>TM1062HUXBT Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER TM1062HUXB PBC I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>TM1062TX3DUA Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER MODULE IEEE1394B I roto i te taonga: 70 pcs</p> <p>RFQ</p>	<p>TM1062FUB Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER MODULE PBC I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>TM1062FSB Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER MODULE PBC I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>TM1062FCA2 Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER PBC I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>TM1062HSCT Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER PBC I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>TM1062HUCT Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER PBC I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>TM1062FSA Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER PBC I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>TM1062FCA1 Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER PBC I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>TM1062HUXB Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER MODULE IEEE1394B I roto i te taonga: 9 pcs</p> <p>RFQ</p>	<p>TM1062HUB5 Kaihanga: Pulse Electronics Corporation Whakaahuatanga: TRANSCEIVER TM1062HUB5 PBC I roto i te taonga: Out stock</p> <p>RFQ</p>

