



TDK Corporation

HHM1733B1

Tau Wae:

HHM1733B1

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 4.9GHZ-5.95GHZ 50/50 0603

Ngā Rauemi:

 HHM1733B1.pdf

RoHS Tūnga

 Whakahaerehia te kore utu / RoHS

Tuhinga mai i

Hong Kong


Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o HHM1733B1

TAU WAE	HHM1733B1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 4.9GHZ-5.95GHZ 50/50 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	 HHM1733B1.pdf
RAUPAPA	HHM
HOKI HOKI (MIN)	10dB
RAWEHANGA PUTANGA	180° ±10°
PACKAGING	Cut Tape (CT)
PAA / CASE	0603 (1608 Metric)
ĒTAHI INGOA	445-3996-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE TAE KAITUKU TAEKE	12 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	1.2dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 50 Ohm
MAHINGA RAWE	4.9GHz ~ 5.95GHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 4.9GHz ~ 5.95GHz 50 / 50 Ohm 0603 (1608 Metric)

Ngā tūtohu e hāngai ana

TDK Corporation HHM1733B1	Kaitoha HHM1733B1	Kaiwhakarato HHM1733B1
Utu HHM1733B1	Pikitia HHM1733B1	Whakaahua HHM1733B1
HHM1733B1 Pepa Raraunga PDF	HHM1733B1 Tango Whakahoki	Tapunga HHM1733B1
Hokona HHM1733B1	Hokona HHM1733B1	Hokona TDK Corporation HHM1733B1
TDK Corporation HHM1733B1	Kaiwhakarato TDK Corporation	Kaitoha Kaatawhai TDK Corporation
TDK Corporation HHM1733B1		

Ngā Hua e hāngai ana

 <p>HHM1775D1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.1GHZ-4.9GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM1732B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/100 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>HHM1731F1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.71-1.88GHZ 50/200 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM1749S1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.71-1.99GHZ 50/100 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>HHM1752A2 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/200 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM1727D1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.3GHZ-3.9GHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>HHM1763B2 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 880MHZ-960MHZ 50/150 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM1726N1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-915MHZ 50/100 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>HHM17168B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.4GHZ-3.8GHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM1776B2 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-894MHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>HHM1726P1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 880MHZ-960MHZ 50/100 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>HHM1776B3 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 880MHZ-960MHZ 50/50 0603 I roto i te taonga: Out stock</p> <p>RFQ</p>