

N/A

## TPS3813K33MDBVREP

Tau Wae: TPS3813K33MDBVREP  
 Kaihanga / Waitohu: N/A  
 Whakaahuatanga hua: IC PROC SUPERVISORY CIRC SOT23-6  
 Ngā Rauemi:  
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS  
 Tuhinga mai i: Hong Kong  
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS



**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o TPS3813K33MDBVREP

TAU WAE	TPS3813K33MDBVREP
KAIHANGA	N/A
WHAKAAHUATANGA	IC PROC SUPERVISORY CIRC SOT23-6
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
PUTANGA - TAE	2.93V
MOMO	Simple Reset/Power-On Reset
PŪRERE PŪRERE WHAKARATO	SOT-23-6
RAUPAPA	-
TAUTUHI TAUTUHI	20 ms Minimum
TAUTUHI ANŌ	Active Low
PACKAGING	Cut Tape (CT)
PAA / CASE	SOT-23-6
WHAKAPUTA	Open Drain or Open Collector
ĒTAHI INGOA	296-22441-1
TAE MAHI	-55°C ~ 125°C (TA)
TE MAHA O NGA TAUMAHA AROTURUKI	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	Supervisor Open Drain or Open Collector 1 Channel SOT-23-6
TAU WAE TUAKIRI	TPS3813

### Ngā tūtohu e hāngai ana

TPS3813K33MDBVREP	Kaitoha TPS3813K33MDBVREP	Kaiwhakarato TPS3813K33MDBVREP
Utu TPS3813K33MDBVREP	Pikitia TPS3813K33MDBVREP	Whakaahua TPS3813K33MDBVREP
TPS3813K33MDBVREP Pepa Raraunga PDF	TPS3813K33MDBVREP Tango Whakahoki	Tapunga TPS3813K33MDBVREP
Hokona TPS3813K33MDBVREP	Hokona TPS3813K33MDBVREP	Hokona TPS3813K33MDBVREP
TPS3813K33MDBVREP	Kaiwhakarato	Kaitoha Kaatawhai

### Ngā Hua e hāngai ana

<p><b>TPS3813L30DBVR</b>                  Kaihanga: N/A                  Whakaahuatanga: IC SUPPLY MONITOR 2.64V SOT-23-6                  I roto i te taonga: 53322 pcs</p> <p><b>RFQ</b></p>	<p><b>TPS3813L30DBVRG4</b>                  Kaihanga: N/A                  Whakaahuatanga: IC 2.64V SUPPLY MONITOR SOT-23-6                  I roto i te taonga: 66932 pcs</p> <p><b>RFQ</b></p>
<p><b>TPS3813L30DBVT</b>                  Kaihanga: Texas Instruments                  Whakaahuatanga: IC 2.64V SUPPLY MONITOR SOT-23-6                  I roto i te taonga: 64144 pcs</p> <p><b>RFQ</b></p>	<p><b>TPS3813K33QDBVRQ1</b>                  Kaihanga: N/A                  Whakaahuatanga: IC PROC SUPERVISOR CIRC SOT23-6                  I roto i te taonga: 100305 pcs</p> <p><b>RFQ</b></p>
<p><b>TPS3813K33DBVT</b>                  Kaihanga: N/A                  Whakaahuatanga: IC 2.93V SUPPLY MONITOR SOT-23-6                  I roto i te taonga: 80937 pcs</p> <p><b>RFQ</b></p>	<p><b>TPS3813K33DBVTG4</b>                  Kaihanga: N/A                  Whakaahuatanga: IC 2.93V SUPPLY MONITOR SOT-23-6                  I roto i te taonga: 73992 pcs</p> <p><b>RFQ</b></p>
<p><b>TPS3813K33DBVRG4</b>                  Kaihanga: N/A                  Whakaahuatanga: IC 2.93V SUPPLY MONITOR SOT-23-6                  I roto i te taonga: 69907 pcs</p> <p><b>RFQ</b></p>	<p><b>TPS3813K33DBVR</b>                  Kaihanga: N/A                  Whakaahuatanga: IC 2.93V SUPPLY MONITOR SOT-23-6                  I roto i te taonga: 69284 pcs</p> <p><b>RFQ</b></p>
<p><b>TPS3813J25DBVTG4</b>                  Kaihanga: N/A                  Whakaahuatanga: IC 2.25V SUPPLY MONITOR SOT-23-6                  I roto i te taonga: 77178 pcs</p> <p><b>RFQ</b></p>	<p><b>TPS3813L30DBVT</b>                  Kaihanga: N/A                  Whakaahuatanga: IC 2.64V SUPPLY MONITOR SOT-23-6                  I roto i te taonga: 65700 pcs</p> <p><b>RFQ</b></p>
<p><b>TPS3813J25DBVT</b>                  Kaihanga: N/A                  Whakaahuatanga: IC 2.25V SUPPLY MONITOR SOT-23-6                  I roto i te taonga: 84732 pcs</p> <p><b>RFQ</b></p>	<p><b>TPS3813L30DBVTG4</b>                  Kaihanga: N/A                  Whakaahuatanga: IC 2.64V SUPPLY MONITOR SOT-23-6                  I roto i te taonga: 72737 pcs</p> <p><b>RFQ</b></p>