



Maxim Integrated

DS21372TN+

Tau Wae:

DS21372TN+

Kaihanga / Waitohu:

Maxim Integrated

Whakaahuatanga hua

IC TESTER BIT ERROR 3.3V 32-TQFP

Ngā Rauemi:

DS21372TN+.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o DS21372TN+

TAU WAE	DS21372TN+
KAIHANGA	Maxim Integrated
WHAKAAHUATANGA	IC TESTER BIT ERROR 3.3V 32-TQFP
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	DS21372TN+.pdf
TUHINGA O MUA	3 V ~ 3.6 V
PŪRERE PŪRERE WHAKARATO	32-TQFP (7x7)
RAUPAPA	-
PACKAGING	Tray
PAA / CASE	32-TQFP
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
ATANGA	T1
KEI ROTO	Error Counter, Pattern Generator and Detector
MAHINGA	Bit Error Rate Tester (BERT)
WHAKAAHUATANGA TAIPITOPITO	Telecom IC Bit Error Rate Tester (BERT) 32-TQFP (7x7)
I TEIE NEI - TE TUKU	10mA
TAU WAE TUAKIRI	DS21372

Ngā tūtohu e hāngai ana

Maxim Integrated DS21372TN+	Kaitoha DS21372TN+	Kaiwhakaratō DS21372TN+
Utu DS21372TN+	Pikitia DS21372TN+	Whakaahua DS21372TN+
DS21372TN+ Pepa Raraunga PDF	DS21372TN+ Tango Whakahoki	Tapunga DS21372TN+
Hokona DS21372TN+	Hokona DS21372TN+	Hokona Maxim Integrated DS21372TN+
Maxim Integrated DS21372TN+	Kaiwhakaratō Maxim Integrated	Kaitoha Kaatawhai Maxim Integrated
Maxim Integrated DS21372TN+		

Ngā Hua e hāngai ana

<p>DS21354LC1+ Kaihanga: Maxim Integrated Whakaahuatanga: IC TXRX E1 3.3V 100-LQFP I roto i te taonga: 18 pcs</p> <p>RFQ</p>	<p>DS21372T+ Kaihanga: Maxim Integrated Whakaahuatanga: IC TESTER BIT ERROR 3.3V 32-TQFP I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>DS2141AQ+T&R Kaihanga: Maxim Integrated Whakaahuatanga: IC CONTROLLER T1 5V 44-PLCC I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>DS2141AQ/T&R Kaihanga: Maxim Integrated Whakaahuatanga: IC CONTROLLER T1 5V 44-PLCC I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>DS2141A Kaihanga: Maxim Integrated Whakaahuatanga: IC CONTROLLER T1 5V 40-DIP I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>DS21372T Kaihanga: Maxim Integrated Whakaahuatanga: IC TESTER BIT ERROR 3.3V 32-TQFP I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>DS2141AQ+ Kaihanga: Maxim Integrated Whakaahuatanga: IC CONTROLLER T1 5V 44-PLCC I roto i te taonga: 32 pcs</p> <p>RFQ</p>	<p>DS2141AQ Kaihanga: Maxim Integrated Whakaahuatanga: IC CONTROLLER T1 5V 44-PLCC I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>DS21372TN Kaihanga: Maxim Integrated Whakaahuatanga: IC TESTER BIT ERROR 3.3V 32-TQFP I roto i te taonga: Out stock</p> <p>RFQ</p>	<p>DS2141AN Kaihanga: Maxim Integrated Whakaahuatanga: IC CONTROLLER T1 5V 40-DIP I roto i te taonga: Out stock</p> <p>RFQ</p>
<p>DS21354LN+ Kaihanga: Maxim Integrated Whakaahuatanga: IC TXRX E1 1-CHIP 3.3V 100-LQFP I roto i te taonga: 1 pcs</p> <p>RFQ</p>	<p>DS21354LN Kaihanga: Maxim Integrated Whakaahuatanga: IC TXRX E1 1-CHIP 3.3V 100-LQFP I roto i te taonga: Out stock</p> <p>RFQ</p>

