

N/A

CDCV857DGG

Tau Wae: CDCV857DGG
 Kaihanga / Waitohu: N/A
 Whakaahuatanga hua: IC SSTL-II PLL CLK-DRVR 48TSSOP
 Ngā Rauemi:
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS



No Picture

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o CDCV857DGG

TAU WAE	CDCV857DGG
KAIHANGA	N/A
WHAKAAHUATANGA	IC SSTL-II PLL CLK-DRVR 48TSSOP
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	2.3 V ~ 2.7 V
MOMO	PLL Clock Driver
PŪRERE PŪRERE WHAKARATO	48-TSSOP
RAUPAPA	-
RATONGA - WHAKAURU: WHAKAPUTA	1:10
PACKAGING	Tube
PAA / CASE	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
WHAKAPUTA	Clock
ĒTAHI INGOA	296-24143-5 CDCV857DGG-ND
TAE MAHI	0°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	2 (1 Year)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAURU	Clock
TAUTANGA - MAX	200MHz
KAWEWEHE / WHAKANAO	No/No
MOTUHAKE - WHAKAURU: WHAKAPUTA	Yes/Yes
TAU WAE TUAKIRI	CDCV857

Ngā tūtohu e hāngai ana

CDCV857DGG	Kaitoha CDCV857DGG	Kaiwhakarato CDCV857DGG
Utu CDCV857DGG	Pikitia CDCV857DGG	Whakaahua CDCV857DGG
CDCV857DGG Pepa Raraunga PDF	CDCV857DGG Tango Whakahoki	Tapunga CDCV857DGG
Hokona CDCV857DGG	Hokona CDCV857DGG	Hokona CDCV857DGG
CDCV857DGG	Kaiwhakarato	Kaitoha Kaatawhai

Ngā Hua e hāngai ana

<p>CDCV857DGGRG4 Kaihanga: N/A Whakaahuatanga: IC SSTL-II PLL CLK-DRVR 48TSSOP I roto i te taonga: 5405 pcs</p> <p>RFQ</p>	<p>CDCVF111FNG4 Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:9 650MHZ 28PLCC I roto i te taonga: 5389 pcs</p> <p>RFQ</p>
<p>CDCV857DGGG4 Kaihanga: N/A Whakaahuatanga: IC SSTL-II PLL CLK-DRVR 48TSSOP I roto i te taonga: 4677 pcs</p> <p>RFQ</p>	<p>CDCV857BGQLR Kaihanga: N/A Whakaahuatanga: IC 2.5V PLL CLOCK DRVR 56-BGA I roto i te taonga: 4617 pcs</p> <p>RFQ</p>
<p>CDCV857BIDGGR Kaihanga: N/A Whakaahuatanga: IC SSTL-II PLL CLK-DRVR 48TSSOP I roto i te taonga: 16291 pcs</p> <p>RFQ</p>	<p>CDCV857BDGGRG4 Kaihanga: N/A Whakaahuatanga: IC SSTL-II PLL CLK-DRVR 48TSSOP I roto i te taonga: 22822 pcs</p> <p>RFQ</p>
<p>CDCVF111FNR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:9 650MHZ 28PLCC I roto i te taonga: 7790 pcs</p> <p>RFQ</p>	<p>CDCV857BIDGGRG4 Kaihanga: N/A Whakaahuatanga: IC SSTL-II PLL CLK-DRVR 48TSSOP I roto i te taonga: 19369 pcs</p> <p>RFQ</p>
<p>CDCV857DGGR Kaihanga: N/A Whakaahuatanga: IC SSTL-II PLL CLK-DRVR 48-TSSOP I roto i te taonga: 5363 pcs</p> <p>RFQ</p>	<p>CDCV857BIDGGG4 Kaihanga: N/A Whakaahuatanga: IC SSTL-II PLL CLK-DRVR 48-TSSOP I roto i te taonga: 8726 pcs</p> <p>RFQ</p>
<p>CDCV857BIDGG Kaihanga: N/A Whakaahuatanga: IC SSTL-II PLL CLK-DRVR 48-TSSOP I roto i te taonga: 10910 pcs</p> <p>RFQ</p>	<p>CDCVF111FN Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:9 650MHZ 28PLCC I roto i te taonga: 6603 pcs</p> <p>RFQ</p>