

N/A

## LMK00304SQX/NOPB

Tau Wae: LMK00304SQX/NOPB  
 Kaihanga / Waitohu: N/A  
 Whakaahuatanga hua: IC CLK BUFFER 3:5 3.1GHZ 32WQFN  
 Ngā Rauemi:  
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS  
 Tuhinga mai i: Hong Kong  
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS



**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o LMK00304SQX/NOPB

TAU WAE	LMK00304SQX/NOPB
KAIHANGA	N/A
WHAKAAHUATANGA	IC CLK BUFFER 3:5 3.1GHZ 32WQFN
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	3.15 V ~ 3.45 V
MOMO	Fanout Buffer (Distribution), Multiplexer, Translator
PŪRERE PŪRERE WHAKARATO	32-WQFN (5x5)
RAUPAPA	-
RATONGA - WHAKAURU: WHAKAPUTA	3:5
PACKAGING	Tape & Reel (TR)
PAA / CASE	32-WFQFN Exposed Pad
WHAKAPUTA	HCSL, LVCMOS, LVDS, LVPECL
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAURU	CML, HCSL, HSTL, LVDS, LVPECL, SSTL, Crystal
TAUTANGA - MAX	3.1GHz
MOTUHAKE - WHAKAURU: WHAKAPUTA	Yes/Yes
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution), Multiplexer, Translator IC 3:5 3.1GHz 32-WFQFN Exposed Pad
TAU WAE TUAKIRI	LMK00304

### Ngā tūtohu e hāngai ana

LMK00304SQX/NOPB	Kaitoha LMK00304SQX/NOPB	Kaiwhakarato LMK00304SQX/NOPB
Utu LMK00304SQX/NOPB	Pikitia LMK00304SQX/NOPB	Whakaahua LMK00304SQX/NOPB
LMK00304SQX/NOPB Pepa Raraunga PDF	LMK00304SQX/NOPB Tango Whakahoki	Tapunga LMK00304SQX/NOPB
Hokona LMK00304SQX/NOPB	Hokona LMK00304SQX/NOPB	Hokona LMK00304SQX/NOPB
LMK00304SQX/NOPB	Kaiwhakarato	Kaitoha Kaatawhai

### Ngā Hua e hāngai ana

<p><b>LMK00306SQ/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 3:7 3.1GHZ 36WQFN                  I roto i te taonga: 15141 pcs  <a href="#">RFQ</a></p>	<p><b>LMK00301SQ/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 3:10 3.1GHZ 48WQFN                  I roto i te taonga: 16276 pcs  <a href="#">RFQ</a></p>
<p><b>LMK00306SQE/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 3:7 3.1GHZ 36WQFN                  I roto i te taonga: 15164 pcs  <a href="#">RFQ</a></p>	<p><b>LMK00308SQ/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 3:9 3.1GHZ 40WQFN                  I roto i te taonga: 16225 pcs  <a href="#">RFQ</a></p>
<p><b>LMK00308EVM/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: BOARD EVAL FOR LMK00308                  I roto i te taonga: 337 pcs  <a href="#">RFQ</a></p>	<p><b>LMK00304SQ/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 3:5 3.1GHZ 32WQFN                  I roto i te taonga: 24218 pcs  <a href="#">RFQ</a></p>
<p><b>LMK00304SQE/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 3:5 3.1GHZ 32WQFN                  I roto i te taonga: 16840 pcs  <a href="#">RFQ</a></p>	<p><b>LMK00306EVM/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: BOARD EVAL FOR LMK00306                  I roto i te taonga: 409 pcs  <a href="#">RFQ</a></p>
<p><b>LMK00301SQX/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 3:10 3.1GHZ 48WQFN                  I roto i te taonga: 17670 pcs  <a href="#">RFQ</a></p>	<p><b>LMK00304EVM/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: BOARD EVAL FOR LMK00304                  I roto i te taonga: 425 pcs  <a href="#">RFQ</a></p>
<p><b>LMK00301SQE/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 3:10 3.1GHZ 48WQFN                  I roto i te taonga: 10236 pcs  <a href="#">RFQ</a></p>	<p><b>LMK00306SQX/NOPB</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 3:7 3.1GHZ 36WQFN                  I roto i te taonga: 19578 pcs  <a href="#">RFQ</a></p>