



Micrel / Microchip Technology

SY58034UMI

Tau Wae:

SY58034UMI

Kaihanga / Waitohu:

Micrel / Microchip Technology

Whakaahuatanga hua

IC CLK BUFFER 2:6 7.5GHZ 32MLF

Ngā Rauemi:

 SY58034UMI.pdf

RoHS Tūnga

 Kei roto nga rangatira / RoHS kaore i te ture

Tuhinga mai i

Hong Kong


Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o SY58034UMI

TAU WAE	SY58034UMI
KAIHANGA	Micrel / Microchip Technology
WHAKAAHUATANGA	IC CLK BUFFER 2:6 7.5GHZ 32MLF
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
PEPA RARAUNGA	 SY58034UMI.pdf
TUHINGA O MUA	2.375 V ~ 3.6 V
MOMO	Fanout Buffer (Distribution), Multiplexer
PŪRERE PŪRERE WHAKARATO	32-MLF® (5x5)
RAUPAPA	Precision Edge®
RATONGA - WHAKAURU: WHAKAPUTA	2:6
PACKAGING	Tube
PAA / CASE	32-VFQFN Exposed Pad, 32-MLF®
WHAKAPUTA	CML
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAURU	CML, LVDS, PECL
TAUTANGA - MAX	7.5GHz
MOTUHAKE - WHAKAURU: WHAKAPUTA	Yes/Yes
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution), Multiplexer IC 2:6 7.5GHz 32-VFQFN Exposed Pad, 32-MLF®
TAU WAE TUAKIRI	SY58034

Ngā tūtohu e hāngai ana

Micrel / Microchip Technology SY58034UMI	Kaitoha SY58034UMI	Kaiwhakarato SY58034UMI
Utu SY58034UMI	Pikitia SY58034UMI	Whakaahua SY58034UMI
SY58034UMI Pepa Raraunga PDF	SY58034UMI Tango Whakahoki	Tapunga SY58034UMI
Hokona SY58034UMI	Hokona SY58034UMI	Hokona Micrel / Microchip Technology SY58034UMI
Micrel / Microchip Technology SY58034UMI	Kaiwhakarato Micrel / Microchip Technology	Kaitoha Kaatawhai Micrel / Microchip Technology
Micrel / Microchip Technology SY58034UMI	Microchip Technology SY58034UMI	Roving Networks / Microchip Technology SY58034UMI

Ngā Hua e hāngai ana

 <p>SY58033UMI-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>SY58034UMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 7.5GHZ 32MLF I roto i te taonga: 3 pcs</p> <p>RFQ</p>
 <p>SY58035UMI Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 5.5GHZ 32MLF I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>SY58036UMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 7GHZ 32MLF I roto i te taonga: 141 pcs</p> <p>RFQ</p>
 <p>SY58034UMI-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 7.5GHZ 32MLF I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>SY58034UMG-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 7.5GHZ 32MLF I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>SY58033UMI Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>SY58033UMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: 194 pcs</p> <p>RFQ</p>
 <p>SY58035UMG-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 5.5GHZ 32MLF I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>SY58033UMG-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>SY58035UMI-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 5.5GHZ 32MLF I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>SY58035UMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 5.5GHZ 32MLF I roto i te taonga: 360 pcs</p> <p>RFQ</p>