



SICK

DGS35-LJ402048

Tau Wae:	DGS35-LJ402048
Kaihanga / Waitohu:	SICK
Whakaahuatanga hua	ROTARY ENCODR INCREMENT 2048PPR
Ngā Rauemi:	
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS



TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o DGS35-LJ402048

TAU WAE	DGS35-LJ402048
KAIHANGA	SICK
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 2048PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
PEPA RARAUNGA	
TUHINGA O MUA	5V
KĀHUA WHAKAMUTUNGA	Connector
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	2048
MOMO PUTANGA	-
ĒTAHI INGOA	1059232
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
TE TAE KAITUKU TAEKE	3 Weeks
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

Ngā tūtohu e hāngai ana

SICK DGS35-LJ402048	Kaitoha DGS35-LJ402048	Kaiwhakarato DGS35-LJ402048
Utu DGS35-LJ402048	Pikitia DGS35-LJ402048	Whakaahua DGS35-LJ402048
DGS35-LJ402048 Pepa Raraunga PDF	DGS35-LJ402048 Tango Whakahoki	Tapunga DGS35-LJ402048
Hokona DGS35-LJ402048	Hokona DGS35-LJ402048	Hokona SICK DGS35-LJ402048
SICK DGS35-LJ402048	Kaiwhakarato SICK	Kaitoha Kaatawhai SICK
SICK DGS35-LJ402048		

Ngā Hua e hāngai ana

 <p>DGS35-YH208192 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 8192PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-LLK03600 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 3600PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-LH401024 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-LH402500 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-LKK01024 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-LHK02048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-LK202048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-LLK02048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-LHK02500 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-9KM00600 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENTAL 600PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-LH404096 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-LKK02500 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p>RFQ</p>