

N/A

CDCLVP2102RGTT

Tau Wae:

CDCLVP2102RGTT

Kaihanga / Waitohu:

N/A

Whakaahuatanga hua

IC CLK BUFFER 2:4 2GHZ 16QFN

Ngā Rauemi:

Whakahaerehia te kore utu / RoHS

RoHS Tūnga

Hong Kong

Tuhinga mai i

DHL/Fedex/TNT/UPS/EMS

Te Ara Tuhi

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o CDCLVP2102RGTT

TAU WAE	CDCLVP2102RGTT
KAIHANGA	N/A
WHAKAAHUATANGA	IC CLK BUFFER 2:4 2GHZ 16QFN
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	2.375 V ~ 3.6 V
MOMO	Fanout Buffer (Distribution)
PŪRERE PŪRERE WHAKARATO	16-QFN (3x3)
RAUPAPA	-
RATONGA - WHAKAURU: WHAKAPUTA	2:4
PACKAGING	Tape & Reel (TR)
PAA / CASE	16-VFQFN Exposed Pad
WHAKAPUTA	LVPECL
ĒTAHI INGOA	296-25284-2
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	2 (1 Year)
TE TAE KAITUKU TAEKE	10 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAURU	LVC MOS, LVDS, LVPECL, LVTTL
TAUTANGA - MAX	2GHz
MOTUHAKE - WHAKAURU: WHAKAPUTA	Yes/Yes
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution) IC 2:4 2GHZ 16-VFQFN Exposed Pad
TAU WAE TUAKIRI	CDCLVP2102

Ngā tūtohu e hāngai ana

CDCLVP2102RGTT	Kaitoha CDCLVP2102RGTT	Kaiwhakarato CDCLVP2102RGTT
Utu CDCLVP2102RGTT	Pikitia CDCLVP2102RGTT	Whakaahua CDCLVP2102RGTT
CDCLVP2102RGTT Pepa Raraunga PDF	CDCLVP2102RGTT Tango Whakahoki	Tapunga CDCLVP2102RGTT
Hokona CDCLVP2102RGTT	Hokona CDCLVP2102RGTT	Hokona CDCLVP2102RGTT
CDCLVP2102RGTT	Kaiwhakarato	Kaitoha Kaatawhai

Ngā Hua e hāngai ana

<p>CDCLVP1216RGZR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:16 2GHZ 48VQFN I roto i te taonga: 8987 pcs</p> <p>RFQ</p>	<p>CDCLVP2102RGTR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:4 2GHZ 16QFN I roto i te taonga: 25465 pcs</p> <p>RFQ</p>
<p>CDCLVP2104RHDR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:8 2GHZ 28VQFN I roto i te taonga: 15817 pcs</p> <p>RFQ</p>	<p>CDCLVP2106RHAT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:12 2GHZ 40VQFN I roto i te taonga: 11141 pcs</p> <p>RFQ</p>
<p>CDCLVP2102EVM Kaihanga: N/A Whakaahuatanga: EVALUATION MODULE FOR CDCLVP2102 I roto i te taonga: 567 pcs</p> <p>RFQ</p>	<p>CDCLVP1216EVM Kaihanga: N/A Whakaahuatanga: EVAL MODULE FOR CDCLVP1216 I roto i te taonga: 672 pcs</p> <p>RFQ</p>
<p>CDCLVP2106RHAR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:12 2GHZ 40VQFN I roto i te taonga: 12796 pcs</p> <p>RFQ</p>	<p>CDCLVP2104RHDT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:8 2GHZ 28VQFN I roto i te taonga: 15968 pcs</p> <p>RFQ</p>
<p>CDCLVP2104EVM Kaihanga: N/A Whakaahuatanga: EVAL MODULE FOR CDCLVP2104 I roto i te taonga: 582 pcs</p> <p>RFQ</p>	<p>CDCLVP2106EVM Kaihanga: N/A Whakaahuatanga: EVAL MODULE FOR CDCLVP2106 I roto i te taonga: 684 pcs</p> <p>RFQ</p>
<p>CDCLVP1212RHAT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:12 2GHZ 40VQFN I roto i te taonga: 11436 pcs</p> <p>RFQ</p>	<p>CDCLVP1216RGZT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:16 2GHZ 48VQFN I roto i te taonga: 8435 pcs</p> <p>RFQ</p>