

N/A

CDCLVP2106RHAR

Tau Wae:	CDCLVP2106RHAR
Kaihanga / Waitohu:	N/A
Whakaahuatanga hua	IC CLK BUFFER 1:12 2GHZ 40VQFN
Ngā Rauemi:	
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o CDCLVP2106RHAR

TAU WAE	CDCLVP2106RHAR
KAIHANGA	N/A
WHAKAAHUATANGA	IC CLK BUFFER 1:12 2GHZ 40VQFN
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	2.375 V ~ 3.6 V
MOMO	Fanout Buffer (Distribution)
PŪRERE PŪRERE WHAKARATO	40-VQFN (6x6)
RAUPAPA	-
RATONGA - WHAKAURU: WHAKAPUTA	1:12
PACKAGING	Tape & Reel (TR)
PAA / CASE	40-VFQFN Exposed Pad
WHAKAPUTA	LVPECL
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
TE TAE KAITUKU TAEKE	6 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAURU	LVC MOS, LVDS, LVPECL, LV TTL
TAUTANGA - MAX	2GHz
MOTUHAKE - WHAKAURU: WHAKAPUTA	Yes/Yes
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution) IC 1:12 2GHz 40-VFQFN Exposed Pad
TAU WAE TUAKIRI	CDCLVP2106

Ngā tūtohu e hāngai ana

CDCLVP2106RHAR	Kaitoha CDCLVP2106RHAR	Kaiwhakarato CDCLVP2106RHAR
Utu CDCLVP2106RHAR	Pikitia CDCLVP2106RHAR	Whakaahua CDCLVP2106RHAR
CDCLVP2106RHAR Pepa Raraunga PDF	CDCLVP2106RHAR Tango Whakahoki	Tapunga CDCLVP2106RHAR
Hokona CDCLVP2106RHAR	Hokona CDCLVP2106RHAR	Hokona CDCLVP2106RHAR
CDCLVP2106RHAR	Kaiwhakarato	Kaitoha Kaatawhai

Ngā Hua e hāngai ana

<p>CDCLVP2104RHDT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:8 2GHZ 28VQFN I roto i te taonga: 15968 pcs</p> <p>RFQ</p>	<p>CDCLVP215RHBR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:5 3.5GHZ 32QFN I roto i te taonga: 15920 pcs</p> <p>RFQ</p>
<p>CDCLVP2108RGZR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:16 2GHZ 48VQFN I roto i te taonga: 9163 pcs</p> <p>RFQ</p>	<p>CDCLVP2108RGZT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:16 2GHZ 48VQFN I roto i te taonga: 7998 pcs</p> <p>RFQ</p>
<p>CDCLVP2104RHDR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:8 2GHZ 28VQFN I roto i te taonga: 15817 pcs</p> <p>RFQ</p>	<p>CDCLVP2106RHAT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:12 2GHZ 40VQFN I roto i te taonga: 11141 pcs</p> <p>RFQ</p>
<p>CDCLVP2102RGTT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:4 2GHZ 16QFN I roto i te taonga: 20365 pcs</p> <p>RFQ</p>	<p>CDCLVP215RHBT Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 1:5 3.5GHZ 32QFN I roto i te taonga: 12385 pcs</p> <p>RFQ</p>
<p>CDCLVP2108EVM Kaihanga: N/A Whakaahuatanga: EVAL MODULE FOR CDCLVP2108 I roto i te taonga: 573 pcs</p> <p>RFQ</p>	<p>CDCLVP2102RGTR Kaihanga: N/A Whakaahuatanga: IC CLK BUFFER 2:4 2GHZ 16QFN I roto i te taonga: 25465 pcs</p> <p>RFQ</p>
<p>CDCLVP2106EVM Kaihanga: N/A Whakaahuatanga: EVAL MODULE FOR CDCLVP2106 I roto i te taonga: 684 pcs</p> <p>RFQ</p>	<p>CDCLVP2104EVM Kaihanga: N/A Whakaahuatanga: EVAL MODULE FOR CDCLVP2104 I roto i te taonga: 582 pcs</p> <p>RFQ</p>