

N/A

## CDCLVP2104RHDT

Tau Wae: CDCLVP2104RHDT  
 Kaihanga / Waitohu: N/A  
 Whakaahuatanga hua: IC CLK BUFFER 2:8 2GHZ 28VQFN  
 Ngā Rauemi:  
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS  
 Tuhinga mai i: Hong Kong  
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS



**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o CDCLVP2104RHDT

TAU WAE	CDCLVP2104RHDT
KAIHANGA	N/A
WHAKAAHUATANGA	IC CLK BUFFER 2:8 2GHZ 28VQFN
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	2.375 V ~ 3.6 V
MOMO	Fanout Buffer (Distribution)
PŪRERE PŪRERE WHAKARATO	28-VQFN (5x5)
RAUPAPA	-
RATONGA - WHAKAURU: WHAKAPUTA	2:8
PACKAGING	Tape & Reel (TR)
PAA / CASE	28-VFQFN Exposed Pad
WHAKAPUTA	LVPECL
ĒTAHI INGOA	296-25303-2
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
TE TAE KAITUKU TAEKE	6 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAURU	LVC MOS, LVDS, LVPECL, LVTTL
TAUTANGA - MAX	2GHz
MOTUHAKE - WHAKAURU: WHAKAPUTA	Yes/Yes
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution) IC 2:8 2GHz 28-VFQFN Exposed Pad
TAU WAE TUAKIRI	CDCLVP2104

### Ngā tūtohu e hāngai ana

CDCLVP2104RHDT	Kaitoha CDCLVP2104RHDT	Kaiwhakarato CDCLVP2104RHDT
Utu CDCLVP2104RHDT	Pikitia CDCLVP2104RHDT	Whakaahua CDCLVP2104RHDT
CDCLVP2104RHDT Pepa Raraunga PDF	CDCLVP2104RHDT Tango Whakahoki	Tapunga CDCLVP2104RHDT
Hokona CDCLVP2104RHDT	Hokona CDCLVP2104RHDT	Hokona CDCLVP2104RHDT
CDCLVP2104RHDT	Kaiwhakarato	Kaitoha Kaatawhai

### Ngā Hua e hāngai ana

<p><b>CDCLVP2102EVM</b>                  Kaihanga: N/A                  Whakaahuatanga: EVALUATION MODULE FOR CDCLVP2102                  I roto i te taonga: 567 pcs</p> <p><b>RFQ</b></p>	<p><b>CDCLVP2102RGTR</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 2:4 2GHZ 16QFN                  I roto i te taonga: 25465 pcs</p> <p><b>RFQ</b></p>
<p><b>CDCLVP2108EVM</b>                  Kaihanga: N/A                  Whakaahuatanga: EVAL MODULE FOR CDCLVP2108                  I roto i te taonga: 573 pcs</p> <p><b>RFQ</b></p>	<p><b>CDCLVP2104EVM</b>                  Kaihanga: N/A                  Whakaahuatanga: EVAL MODULE FOR CDCLVP2104                  I roto i te taonga: 582 pcs</p> <p><b>RFQ</b></p>
<p><b>CDCLVP2108RGZR</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 1:16 2GHZ 48VQFN                  I roto i te taonga: 9163 pcs</p> <p><b>RFQ</b></p>	<p><b>CDCLVP2104RHDR</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 2:8 2GHZ 28VQFN                  I roto i te taonga: 15817 pcs</p> <p><b>RFQ</b></p>
<p><b>CDCLVP2106RHAR</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 1:12 2GHZ 40VQFN                  I roto i te taonga: 12796 pcs</p> <p><b>RFQ</b></p>	<p><b>CDCLVP1216RGZT</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 2:16 2GHZ 48VQFN                  I roto i te taonga: 8435 pcs</p> <p><b>RFQ</b></p>
<p><b>CDCLVP2106RHAT</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 1:12 2GHZ 40VQFN                  I roto i te taonga: 11141 pcs</p> <p><b>RFQ</b></p>	<p><b>CDCLVP2102RGTT</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 2:4 2GHZ 16QFN                  I roto i te taonga: 20365 pcs</p> <p><b>RFQ</b></p>
<p><b>CDCLVP2108RGZT</b>                  Kaihanga: N/A                  Whakaahuatanga: IC CLK BUFFER 1:16 2GHZ 48VQFN                  I roto i te taonga: 7998 pcs</p> <p><b>RFQ</b></p>	<p><b>CDCLVP2106EVM</b>                  Kaihanga: N/A                  Whakaahuatanga: EVAL MODULE FOR CDCLVP2106                  I roto i te taonga: 684 pcs</p> <p><b>RFQ</b></p>