

N/A

MSP430G2744IRHA40R

Tau Wae: MSP430G2744IRHA40R
 Kaihanga / Waitohu: N/A
 Whakaahuatanga hua: IC MCU 16BIT 32KB FLASH 40VQFN
 Ngā Rauemi:
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS



TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o MSP430G2744IRHA40R

TAU WAE	MSP430G2744IRHA40R
KAIHANGA	N/A
WHAKAAHUATANGA	IC MCU 16BIT 32KB FLASH 40VQFN
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
NGAOHIHI - WHAKAAETANGA (VCC / VDD)	1.8 V ~ 3.6 V
PŪRERE PŪRERE WHAKARATO	40-VQFN (6x6)
TERE	16MHz
RAUPAPA	MSP430G2xx
RAHI RAM	1K x 8
MOMO MOMO RATONGA	FLASH
RAHI MOTU RATONGA	32KB (32K x 8)
NGA PAPA HANGA REO	Brown-out Detect/Reset, POR, WDT
PACKAGING	Tape & Reel (TR)
PAA / CASE	40-VFQFN Exposed Pad
ĒTAHI INGOA	296-35704-2
OSCILLATOR MOMO	Internal
TAE MAHI	-40°C ~ 85°C (TA)
TAU O I / O	32
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
TE TAE KAITUKU TAEKE	8 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
RAE EEPROM	-
WHAKAAHUATANGA TAIPITOPITO	MSP430 MSP430G2xx Microcontroller IC 16-Bit 16MHz 32KB (32K x 8) FLASH 40-VQFN (6x6)
RARAUNGA RARAUNGA	A/D 12x10b
NUI RAHI	16-Bit
TE TUKATUKA CORE	MSP430
HONONGA	I ² C, IrDA, LINbus, SCI, SPI, UART/USART
TAU WAE TUAKIRI	MSP430G2744

Ngā tūtohu e hāngai ana

MSP430G2744IRHA40R	Kaitoha MSP430G2744IRHA40R	Kaiwhakarato MSP430G2744IRHA40R
Utu MSP430G2744IRHA40R	Pikitia MSP430G2744IRHA40R	Whakaahua MSP430G2744IRHA40R
MSP430G2744IRHA40R Pepa Raraunga PDF	MSP430G2744IRHA40R Tango Whakahoki	Tapunga MSP430G2744IRHA40R
Hokona MSP430G2744IRHA40R	Hokona MSP430G2744IRHA40R	Hokona MSP430G2744IRHA40R
MSP430G2744IRHA40R	Kaiwhakarato	Kaitoha Kaatawhai

Ngā Hua e hāngai ana

<p>MSP430G2744IRHA40T Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 32KB FLASH 40VQFN I roto i te taonga: 58722 pcs</p> <p>RFQ</p>	<p>MSP430G2553IPW28R Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 16KB FLASH 28TSSOP I roto i te taonga: 91768 pcs</p> <p>RFQ</p>
<p>MSP430G2744IYFFR Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 32KB FLASH 49DSBGA I roto i te taonga: 5901 pcs</p> <p>RFQ</p>	<p>MSP430G2744IYFFT Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 32KB FLASH 49DSBGA I roto i te taonga: 5248 pcs</p> <p>RFQ</p>
<p>MSP430G2553IRHB32R Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 16KB FLASH 32VQFN I roto i te taonga: 90511 pcs</p> <p>RFQ</p>	<p>MSP430G2755IRHA40R Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 32KB FLASH 40VQFN I roto i te taonga: 77437 pcs</p> <p>RFQ</p>
<p>MSP430G2553IPW8RQ1 Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 16KB FLASH 28TSSOP I roto i te taonga: 70898 pcs</p> <p>RFQ</p>	<p>MSP430G2755IDA38R Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 32KB FLASH 38TSSOP I roto i te taonga: 65170 pcs</p> <p>RFQ</p>
<p>MSP430G2744IDA38 Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 32KB FLASH 38TSSOP I roto i te taonga: 67575 pcs</p> <p>RFQ</p>	<p>MSP430G2553IRHB32T Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 16KB FLASH 32VQFN I roto i te taonga: 47237 pcs</p> <p>RFQ</p>
<p>MSP430G2744IDA38R Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 32KB FLASH 38TSSOP I roto i te taonga: 75146 pcs</p> <p>RFQ</p>	<p>MSP430G2755IDA38 Kaihanga: N/A Whakaahuatanga: IC MCU 16BIT 32KB FLASH 38TSSOP I roto i te taonga: 73725 pcs</p> <p>RFQ</p>