




**Leader Tech Inc.**




## 48-CBSF-1.0X1.5X0.4

|                     |   |
|---------------------|---|
| Tau Wae:            | 48-CBSF-1.0X1.5X0.4   |
| Kaihanga / Waitohu: | Leader Tech Inc.  |
| Whakaahuatanga hua  | 48-CBSF-1.0X1.5X0.4--48S74--CIRC  |
| Ngā Rauemi:         |  48-CBSF-1.0X1.5X0.4.pdf |
| Tuhinga mai i       | Hong Kong   |
| Te Ara Tuhi         | DHL/Fedex/TNT/UPS/EMS   |

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













### Ngā whakaaturanga o 48-CBSF-1.0X1.5X0.4

|   |   |
|---|---|
| TAU WAE                                 | 48-CBSF-1.0X1.5X0.4   |
| KAIHANGA                                | Leader Tech Inc.  |
| WHAKAAHUATANGA                          | 48-CBSF-1.0X1.5X0.4--48S74--CIRC  |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA |   |
| PEPA RARAUNGA                           |  48-CBSF-1.0X1.5X0.4.pdf |
| WHĀNUI - WHĀNUI                         | 1.000" (25.40mm)  |
| TUHINGA O MUA                           | Vent Holes in Pattern   |
| MOMO                                    | Shield, 2-Piece   |
| RAUPAPA                                 | 40-CBS  |
| MOMO TAE                                | Through Hole  |
| TE TAE KAITUKU TAEKE                    | 4 Weeks   |
| TE ROA - WHĀNUI                         | 1.500" (38.10mm)  |
| TEITEI - WHĀNUI                         | 0.400" (10.16mm)  |
| WHAKAAHUATANGA TAIPITOPITO              | RF Shield Shield, 2-Piece 1.000" (25.40mm) X 1.500" (38.10mm) Vent Holes in Pattern Through Hole            |

### Ngā tūtohu e hāngai ana

|                                       |                                     |   |
|---------------------------------------|-------------------------------------|---|
| Leader Tech Inc. 48-CBSF-1.0X1.5X0.4  | Kaitoha 48-CBSF-1.0X1.5X0.4         | Kaiwhakarato 48-CBSF-1.0X1.5X0.4            |
| Utu 48-CBSF-1.0X1.5X0.4               | Pikitia 48-CBSF-1.0X1.5X0.4         | Whakaahua 48-CBSF-1.0X1.5X0.4               |
| 48-CBSF-1.0X1.5X0.4 Pepa Raraunga PDF | 48-CBSF-1.0X1.5X0.4 Tango Whakahoki | Tapunga 48-CBSF-1.0X1.5X0.4                 |
| Hokona 48-CBSF-1.0X1.5X0.4            | Hokona 48-CBSF-1.0X1.5X0.4          | Hokona Leader Tech Inc. 48-CBSF-1.0X1.5X0.4 |
| Leader Tech Inc. 48-CBSF-1.0X1.5X0.4  | Kaiwhakarato Leader Tech Inc.       | Kaitoha Kaatawhai Leader Tech Inc.          |
| Leader Tech Inc. 48-CBSF-1.0X1.5X0.4  |                                     |   |

### Ngā Hua e hāngai ana

|   |  |
|---|--|
|  <p><b>48-CBSFN-1.0X1.5</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48-CBSFN-1.0X1.5--48S91--CIRCUIT<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>     |  <p><b>48-CBSF-2.5X3.5X0.4</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48-CBSF-2.5X3.5X0.4--48S27--CIRC<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>  |
|  <p><b>48-CBSA-5.5X6.0X0.4</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>     |  <p><b>48-CBSA-5.75X6.0X0.4</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>    |
|  <p><b>48-CBSA-5.5X5.75X0.4</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>    |  <p><b>48-CBSF-1.0X2.75X0.4</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48-CBSF-1.0X2.75X0.4--48S73--CIR<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p> |
|  <p><b>48-CBSA-6.0X6.0X0.4</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>     |  <p><b>48-CBSA-5.75X5.75X0.4</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>   |
|  <p><b>48-CBSA-5.5X5.5X0.4</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48 SERIES CBS SHIELD ASSEMBLY<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>     |  <p><b>48-CBSF-5.0X5.5X0.4</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48-CBSF-5.0X5.5X0.4--48S79--CIRC<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>  |
|  <p><b>48-CBSF-1.25X1.5X0.4</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48-CBSF-1.25X1.5X0.4--48S62--CIR<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p> |  <p><b>48-CBSF-1.25X3.5X0.4</b><br/>Kaihanga: Leader Tech Inc.<br/>Whakaahuatanga: 48-CBSF-1.25X3.5X0.4--48S51--CIR<br/>I roto i te taonga: Out stock</p> <p><b>RFQ</b></p> |