



SICK

## DGS35-YK402048

Tau Wae:	DGS35-YK402048
Kaihanga / Waitohu:	SICK
Whakaahuatanga hua	ROTARY ENCODR INCREMENT 2048PPR
Ngā Rauemi:	
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS


[TONO MO TE WHAKAHUA](#)

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













## Ngā whakaaturanga o DGS35-YK402048

TAU WAE	DGS35-YK402048
KAIHANGA	SICK
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 2048PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
PEPA RARAUNGA	
TUHINGA O MUA	5V
KĀHUA WHAKAMUTUNGA	Connector
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	2048
MOMO PUTANGA	-
ĒTAHI INGOA	1065096
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
TE TAE KAITUKU TAEKE	3 Weeks
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

## Ngā tūtohu e hāngai ana

SICK DGS35-YK402048	Kaitoha DGS35-YK402048	Kaiwhakarato DGS35-YK402048
Utu DGS35-YK402048	Pikitia DGS35-YK402048	Whakaahua DGS35-YK402048
DGS35-YK402048 Pepa Raraunga PDF	DGS35-YK402048 Tango Whakahoki	Tapunga DGS35-YK402048
Hokona DGS35-YK402048	Hokona DGS35-YK402048	Hokona SICK DGS35-YK402048
SICK DGS35-YK402048	Kaiwhakarato SICK	Kaitoha Kaatawhai SICK
SICK DGS35-YK402048		

## Ngā Hua e hāngai ana

 <p><b>DGS35-YHK05000</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-YL202048</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-YK216384</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-YH401024</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-YKN16384</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-YL416384</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-YK201024</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-YKK16384</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-YKK02048</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-YK410000</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 10000PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-YHK02500</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-YHN10000</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 10000PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>