



Sensor Intelligence.

SICK

DGS35-1K200120

Tau Wae:

DGS35-1K200120

Kaihanga / Waitohu:

SICK

Whakaahuatanga hua

ROTARY ENCODR INCREMENTAL 120PPR

Ngā Rauemi:

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS



Sensor Intelligence.

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o DGS35-1K200120

TAU WAE	DGS35-1K200120
KAIHANGA	SICK
WHAKAAHUATANGA	ROTARY ENCODR INCREMENTAL 120PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
PEPA RARAUNGA	
TUHINGA O MUA	4.5 V ~ 5.5 V
KĀHUA WHAKAMUTUNGA	Cable
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	120
MOMO PUTANGA	-
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
TE TAE KAITUKU TAEKE	3 Weeks
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

Ngā tūtohu e hāngai ana

SICK DGS35-1K200120	Kaitoha DGS35-1K200120	Kaiwhakarato DGS35-1K200120
Utu DGS35-1K200120	Pikitia DGS35-1K200120	Whakaahua DGS35-1K200120
DGS35-1K200120 Pepa Raraunga PDF	DGS35-1K200120 Tango Whakahoki	Tapunga DGS35-1K200120
Hokona DGS35-1K200120	Hokona DGS35-1K200120	Hokona SICK DGS35-1K200120
SICK DGS35-1K200120	Kaiwhakarato SICK	Kaitoha Kaatawhai SICK
SICK DGS35-1K200120		

Ngā Hua e hāngai ana

 <p>DGS35-1J405000 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1JK04096 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-1HN02048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1KK05000 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-1HM08192 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 8192PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1KN02048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-1K405000 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1J202048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-1KK01024 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1HN04096 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-1KK02048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1KK02500 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p>RFQ</p>

Manaakitanga © 2020 Kaihoko Motuhake o nga Huinga Tiko - Ocean-Components.com

Ī-mēra: Info@Ocean-Components.com

Wāhi noho: Room 2102, Connaught Commercial Building, 185 Wan Chai Rd, Wan Chai, Hong Kong

