



Sensor Intelligence.

SICK

DGS35-LK202048

Tau Wae:

DGS35-LK202048

Kaihanga / Waitohu:

SICK

Whakaahuatanga hua

ROTARY ENCODR INCREMENT 2048PPR

Ngā Rauemi:

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS



Sensor Intelligence.

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o DGS35-LK202048

TAU WAE	DGS35-LK202048
KAIHANGA	SICK
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 2048PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
PEPA RARAUNGA	
TUHINGA O MUA	5V
KĀHUA WHAKAMUTUNGA	Cable
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	2048
MOMO PUTANGA	-
ĒTAHI INGOA	1085294
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
TE TAE KAITUKU TAEKE	3 Weeks
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

Ngā tūtohu e hāngai ana

SICK DGS35-LK202048	Kaitoha DGS35-LK202048	Kaiwhakarato DGS35-LK202048
Utu DGS35-LK202048	Pikitia DGS35-LK202048	Whakaahua DGS35-LK202048
DGS35-LK202048 Pepa Raraunga PDF	DGS35-LK202048 Tango Whakahoki	Tapunga DGS35-LK202048
Hokona DGS35-LK202048	Hokona DGS35-LK202048	Hokona SICK DGS35-LK202048
SICK DGS35-LK202048	Kaiwhakarato SICK	Kaitoha Kaatawhai SICK
SICK DGS35-LK202048		

Ngā Hua e hāngai ana

 <p>DGS35-LH404096 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-LH402500 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-YH401024 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-LKK01024 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-LHK02500 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-YH208192 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 8192PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-LJ402048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-LH401024 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-LKK02500 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-LHK02048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-LLK03600 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 3600PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-LLK02048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>