

N/A

UCC3817DWG4

Tau Wae: UCC3817DWG4
 Kaihanga / Waitohu: N/A
 Whakaahuatanga hua: IC PFC CTRLR AVERAGE CURR 16SOIC
 Ngā Rauemi:
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS



No Picture

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o UCC3817DWG4

TAU WAE	UCC3817DWG4
KAIHANGA	N/A
WHAKAAHUATANGA	IC PFC CTRLR AVERAGE CURR 16SOIC
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	12 V ~ 17 V
PŪRERE PŪRERE WHAKARATO	16-SOIC
RAUPAPA	-
PACKAGING	Tube
PAA / CASE	16-SOIC (0.295", 7.50mm Width)
TAE MAHI	0°C ~ 70°C
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	2 (1 Year)
ARATAU	Average Current
TE TAE KAITUKU TAEKE	28 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
RAUTANGA - WHAKAWHITI	6kHz ~ 220kHz
WHAKAAHUATANGA TAIPITOPITO	PFC IC Average Current 6kHz ~ 220kHz 16-SOIC
ANEI - TE WHAKAOHO	150µA
TAU WAE TUAKIRI	UCC3817

Ngā tūtohu e hāngai ana

UCC3817DWG4	Kaitoha UCC3817DWG4	Kaiwhakarato UCC3817DWG4
Utu UCC3817DWG4	Pikitia UCC3817DWG4	Whakaahua UCC3817DWG4
UCC3817DWG4 Pepa Raraunga PDF	UCC3817DWG4 Tango Whakahoki	Tapunga UCC3817DWG4
Hokona UCC3817DWG4	Hokona UCC3817DWG4	Hokona UCC3817DWG4
UCC3817DWG4	Kaiwhakarato	Kaitoha Kaatawhai

Ngā Hua e hāngai ana

<p>UCC3817DTR Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 73903 pcs</p> <p>RFQ</p>	<p>UCC3817NG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16DIP I roto i te taonga: 40771 pcs</p> <p>RFQ</p>
<p>UCC3817DWTR Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 71936 pcs</p> <p>RFQ</p>	<p>UCC3817N Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16DIP I roto i te taonga: 44416 pcs</p> <p>RFQ</p>
<p>UCC3817DW Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 59860 pcs</p> <p>RFQ</p>	<p>UCC3817PW Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16TSSOP I roto i te taonga: 5386 pcs</p> <p>RFQ</p>
<p>UCC3817EVM Kaihanga: N/A Whakaahuatanga: EVAL MOD FOR UCC3817-015 I roto i te taonga: 838 pcs</p> <p>RFQ</p>	<p>UCC3817DTRG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 68825 pcs</p> <p>RFQ</p>
<p>UCC3817DG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 36664 pcs</p> <p>RFQ</p>	<p>UCC3817DWTRG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 62718 pcs</p> <p>RFQ</p>
<p>UCC3817D Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16SOIC I roto i te taonga: 51983 pcs</p> <p>RFQ</p>	<p>UCC3817APWRG4 Kaihanga: N/A Whakaahuatanga: IC PFC CTRLR AVERAGE CURR 16TSSOP I roto i te taonga: 5152 pcs</p> <p>RFQ</p>