



SICK

DGS35-1KN02048

Tau Wae:	DGS35-1KN02048
Kaihanga / Waitohu:	SICK
Whakaahuatanga hua	ROTARY ENCODR INCREMENT 2048PPR
Ngā Rauemi:	
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS


[TONO MO TE WHAKAHUA](#)

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o DGS35-1KN02048

TAU WAE	DGS35-1KN02048
KAIHANGA	SICK
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 2048PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
PEPA RARAUNGA	
TUHINGA O MUA	4.5 V ~ 5.5 V
KĀHUA WHAKAMUTUNGA	Cable
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	2048
MOMO PUTANGA	-
ĒTAHI INGOA	1066882
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
TE TAE KAITUKU TAEKE	3 Weeks
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

Ngā tūtohu e hāngai ana

SICK DGS35-1KN02048	Kaitoha DGS35-1KN02048	Kaiwhakarato DGS35-1KN02048
Utu DGS35-1KN02048	Pikitia DGS35-1KN02048	Whakaahua DGS35-1KN02048
DGS35-1KN02048 Pepa Raraunga PDF	DGS35-1KN02048 Tango Whakahoki	Tapunga DGS35-1KN02048
Hokona DGS35-1KN02048	Hokona DGS35-1KN02048	Hokona SICK DGS35-1KN02048
SICK DGS35-1KN02048	Kaiwhakarato SICK	Kaitoha Kaatawhai SICK
SICK DGS35-1KN02048		

Ngā Hua e hāngai ana

 <p>DGS35-1L402500 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1K200120 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENTAL 120PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-1LM01024 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1KK05000 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-1L202500 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1KK02500 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-1KK02048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1KK01024 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-1LN00120 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENTAL 120PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1K405000 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>DGS35-1L202048 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>DGS35-1L204096 Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: Out stock</p> <p>RFQ</p>