



TDK Corporation

## HHM1591D1

Tau Wae:

HHM1591D1

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 350MHZ-470MHZ 50/100 0805

Ngā Rauemi:

 HHM1591D1.pdf

RoHS Tūnga

 Whakahaerehia te kore utu / RoHS

Tuhinga mai i

Hong Kong


Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













### Ngā whakaaturanga o HHM1591D1

TAU WAE	HHM1591D1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 350MHZ-470MHZ 50/100 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	 HHM1591D1.pdf
RAUPAPA	HHM
HOKI HOKI (MIN)	8.5dB
RAWEHANGA PUTANGA	180° ±10°
PACKAGING	Tape & Reel (TR)
PAA / CASE	0805 (2012 Metric)
ĒTAHI INGOA	445-3994-2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE TAE KAITUKU TAEKE	12 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	1.5dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 100 Ohm
MAHINGA RAWE	350MHz ~ 470MHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 350MHz ~ 470MHz 50 / 100 Ohm 0805 (2012 Metric)

### Ngā tūtohu e hāngai ana

TDK Corporation HHM1591D1	Kaitoha HHM1591D1	Kaiwhakarato HHM1591D1
Utu HHM1591D1	Pikitia HHM1591D1	Whakaahua HHM1591D1
HHM1591D1 Pepa Raraunga PDF	HHM1591D1 Tango Whakahoki	Tapunga HHM1591D1
Hokona HHM1591D1	Hokona HHM1591D1	Hokona TDK Corporation HHM1591D1
TDK Corporation HHM1591D1	Kaiwhakarato TDK Corporation	Kaitoha Kaatawhai TDK Corporation
TDK Corporation HHM1591D1		

### Ngā Hua e hāngai ana

 <p><b>HHM1596A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.1GHZ-4.9GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1711E1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.7GHZ 50/100 0603 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1583B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.1GHZ-4.9GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1603A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.7GHZ 50/100 4SMD I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1589E1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 350MHZ-470MHZ 50/200 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1564A4</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-894MHZ 50/200 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1595A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3GHZ-8GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1589B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 470MHZ-710MHZ 6SMD I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1710D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1562B</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 5.15-5.875GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1711D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0603 I roto i te taonga: 503 pcs</p> <p><b>RFQ</b></p>	 <p><b>HHM1570B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>