



TDK Corporation

## HHM1522B1

Tau Wae:

HHM1522B1

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 880MHZ-960MHZ 50/50 0805

Ngā Rauemi:

 HHM1522B1.pdf

RoHS Tūnga

 Whakahaerehia te kore utu / RoHS

Tuhinga mai i

Hong Kong


Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













### Ngā whakaaturanga o HHM1522B1

TAU WAE	HHM1522B1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 880MHZ-960MHZ 50/50 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	 HHM1522B1.pdf
RAUPAPA	HHM
HOKI HOKI (MIN)	12dB
RAWEHANGA PUTANGA	180° ±10°
PACKAGING	Tape & Reel (TR)
PAA / CASE	0805 (2012 Metric)
ĒTAHI INGOA	445-3987-2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE TAE KAITUKU TAEKE	12 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	1.3dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 50 Ohm
MAHINGA RAWE	880MHz ~ 960MHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 880MHz ~ 960MHz 50 / 50 Ohm 0805 (2012 Metric)

### Ngā tūtohu e hāngai ana

TDK Corporation HHM1522B1	Kaitoha HHM1522B1	Kaiwhakarato HHM1522B1
Utu HHM1522B1	Pikitia HHM1522B1	Whakaahua HHM1522B1
HHM1522B1 Pepa Raraunga PDF	HHM1522B1 Tango Whakahoki	Tapunga HHM1522B1
Hokona HHM1522B1	Hokona HHM1522B1	Hokona TDK Corporation HHM1522B1
TDK Corporation HHM1522B1	Kaiwhakarato TDK Corporation	Kaitoha Kaatawhai TDK Corporation
TDK Corporation HHM1522B1		

### Ngā Hua e hāngai ana

 <p><b>HHM1525</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.71GHZ-1.99GHZ 50/50 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1518A3</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.71-1.99GHZ 50/150 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1524B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 880MHZ-960MHZ 50/150 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1524B4</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-894MHZ 50/150 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1521</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/200 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1520A2</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.5GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1523C1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 880MHZ-960MHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1526</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.71-1.99GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1523B3</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-894MHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1517A2</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.5GHZ 50/50 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>
 <p><b>HHM1522A7</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-894MHZ 50/50 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>	 <p><b>HHM1520</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0805 I roto i te taonga: Out stock</p> <p><b>RFQ</b></p>