

N/A

TLK1521IPAPG4

Tau Wae:

TLK1521IPAPG4

Kaihanga / Waitohu:

N/A

Whakaahuatanga hua

IC TXRX 1.3GBPS 18BIT 64-HTQFP

Ngā Rauemi:

Whakahaerehia te kore utu / RoHS

RoHS Tūnga

Hong Kong

Tuhinga mai i

DHL/Fedex/TNT/UPS/EMS

Te Ara Tuhi



TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o TLK1521IPAPG4

TAU WAE	TLK1521IPAPG4
KAIHANGA	N/A
WHAKAAHUATANGA	IC TXRX 1.3GBPS 18BIT 64-HTQFP
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	
TUHINGA O MUA	2.3 V ~ 2.7 V
PŪRERE PŪRERE WHAKARATO	64-HTQFP (10x10)
RAUPAPA	-
PACKAGING	Tray
PAA / CASE	64-TQFP Exposed Pad
MOMO PUTANGA	VML
TAE MAHI	-40°C ~ 85°C (TA)
TAU O NGA HUA	1/18
TAU O NGA UTU	18/1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
MOMO INPUT	LVTTL
MAHINGA	Serializer/Deserializer
WHAKAAHUATANGA TAIPITOPITO	1.3Gbps Serializer/Deserializer 18/1 Input 1/18 Output 64-HTQFP (10x10)
RARAUNGA RARAUNGA	1.3Gbps
TAU WAE TUAKIRI	TLK1521

Ngā tūtohu e hāngai ana

TLK1521IPAPG4	Kaitoha TLK1521IPAPG4	Kaiwhakarato TLK1521IPAPG4
Utu TLK1521IPAPG4	Pikitia TLK1521IPAPG4	Whakaahua TLK1521IPAPG4
TLK1521IPAPG4 Pepa Raraunga PDF	TLK1521IPAPG4 Tango Whakahoki	Tapunga TLK1521IPAPG4
Hokona TLK1521IPAPG4	Hokona TLK1521IPAPG4	Hokona TLK1521IPAPG4
TLK1521IPAPG4	Kaiwhakarato	Kaitoha Kaatawhai

Ngā Hua e hāngai ana

<p>TLK1550-RTL</p> <p>Kaihanga: Fluke Electronics Whakaahuatanga: TEST LEAD BANANA TO ALLIGATOR I roto i te taonga: 255 pcs</p> <p>RFQ</p>	<p>TLK1501IRCPR</p> <p>Kaihanga: N/A Whakaahuatanga: IC TRANSCR 0.6-1.5GBPS 64HVQFP I roto i te taonga: 6992 pcs</p> <p>RFQ</p>
<p>TLK1501IRCPRG4</p> <p>Kaihanga: N/A Whakaahuatanga: IC TRANSCR 0.6-1.5GBPS 64HVQFP I roto i te taonga: 6580 pcs</p> <p>RFQ</p>	<p>TLK2201AIRCPRG4</p> <p>Kaihanga: N/A Whakaahuatanga: IC ETHRNT XCVR 1-1.6GBPS 64HVQFP I roto i te taonga: 5610 pcs</p> <p>RFQ</p>
<p>TLK2201AIRCPRG4</p> <p>Kaihanga: N/A Whakaahuatanga: IC ETHRNT XCVR 1-1.6GBPS 64HVQFP I roto i te taonga: 5643 pcs</p> <p>RFQ</p>	<p>TLK1501EVM</p> <p>Kaihanga: N/A Whakaahuatanga: EVALUATION MOD FOR TLK1501 I roto i te taonga: 128 pcs</p> <p>RFQ</p>
<p>TLK1521IPAP</p> <p>Kaihanga: N/A Whakaahuatanga: IC TXRX 1.3GBPS 18BIT 64-HTQFP I roto i te taonga: 4574 pcs</p> <p>RFQ</p>	<p>TLK2201AIRCPR</p> <p>Kaihanga: N/A Whakaahuatanga: IC ETHRNT XCVR 1-1.6GBPS 64HVQFP I roto i te taonga: 5565 pcs</p> <p>RFQ</p>
<p>TLK1501IRCPG4</p> <p>Kaihanga: N/A Whakaahuatanga: IC TRANSCR 0.6-1.5GBPS 64HVQFP I roto i te taonga: 5111 pcs</p> <p>RFQ</p>	<p>TLK2201AJRGQE</p> <p>Kaihanga: N/A Whakaahuatanga: IC ETHERNT XCVR 1-1.6GBPS 80-BGA I roto i te taonga: 5798 pcs</p> <p>RFQ</p>
<p>TLK1501IRCP</p> <p>Kaihanga: N/A Whakaahuatanga: IC TRANSCR 0.6-1.5GBPS 64HVQFP I roto i te taonga: 5302 pcs</p> <p>RFQ</p>	<p>TLK2201AIRCPR</p> <p>Kaihanga: N/A Whakaahuatanga: IC ETHRNT XCVR 1-1.6GBPS 64HVQFP I roto i te taonga: 4543 pcs</p> <p>RFQ</p>