




Leader Tech Inc.

59-CBSA-2.75X4.75X0.5

Tau Wae:	59-CBSA-2.75X4.75X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	59 SERIES CBS SHIELD ASSEMBLY - PDF 1.59-CBSA-2.75X4.75X0.5.pdf PDF 2.59-CBSA-2.75X4.75X0.5.pdf
Ngā Rauemi:	 Whakahaerehia te kore utu / RoHS
RoHs Tūnga	Hong Kong
Tuhinga mai i	DHL/Fedex/TNT/UPS/EMS
Te Ara Tuhi	

[TONO MO TE WHAKAHUA](#)

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o 59-CBSA-2.75X4.75X0.5

TAU WAE	59-CBSA-2.75X4.75X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	59 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	PDF 1.59-CBSA-2.75X4.75X0.5.pdf PDF 2.59-CBSA-2.75X4.75X0.5.pdf
WHĀNUI - WHĀNUI	2.750" (69.85mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	59-CBSA-2.75X4.75X0.4 59-CBSA-2.75X4.75X0.4-ND
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE TAE KAITUKU TAEKE	2 Weeks
TE ROA - WHĀNUI	4.750" (120.65mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 2.750" (69.85mm) X 4.750" (120.65mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 59-CBSA-2.75X4.75X0.5	Kaitoha 59-CBSA-2.75X4.75X0.5	Kaiwhakarato 59-CBSA-2.75X4.75X0.5
Utu 59-CBSA-2.75X4.75X0.5	Pikitia 59-CBSA-2.75X4.75X0.5	Whakaahua 59-CBSA-2.75X4.75X0.5
59-CBSA-2.75X4.75X0.5 Pepa Raraunga PDF	59-CBSA-2.75X4.75X0.5 Tango Whakahoki	Tapunga 59-CBSA-2.75X4.75X0.5
Hokona 59-CBSA-2.75X4.75X0.5	Hokona 59-CBSA-2.75X4.75X0.5	Hokona Leader Tech Inc. 59-CBSA-2.75X4.75X0.5
Leader Tech Inc. 59-CBSA-2.75X4.75X0.5	Kaiwhakarato Leader Tech Inc.	Kaitoha Kaatawhai Leader Tech Inc.
Leader Tech Inc. 59-CBSA-2.75X4.75X0.5		

Ngā Hua e hāngai ana

 <p>59-CBSA-2.75X4.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>59-CBSA-2.75X3.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>59-CBSA-2.75X5.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>59-CBSA-2.75X5.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>59-CBSA-2.75X3.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>59-CBSA-2.75X4.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>59-CBSA-2.75X5.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>59-CBSA-2.75X5.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>59-CBSA-2.75X3.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>59-CBSA-3.0X3.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>59-CBSA-2.75X4.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>59-CBSA-2.75X6.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock</p> <p>RFQ</p>