



Intersil

ISL59910IRZ

Tau Wae:

ISL59910IRZ

Kaihanga / Waitohu:

Intersil

Whakaahuatanga hua

IC RCVR/EQUALZR TRPL DIFF 28-QFN

Ngā Rauemi:

 ISL59910IRZ.pdf

RoHS Tūnga

 Whakahaerehia te kore utu / RoHS

Tuhinga mai i

Hong Kong


Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o ISL59910IRZ

TAU WAE	ISL59910IRZ
KAIHANGA	Intersil
WHAKAAHUATANGA	IC RCVR/EQUALZR TRPL DIFF 28-QFN
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	 ISL59910IRZ.pdf
TUHINGA O MUA	5V
MOMO	Receiver
PŪRERE PŪRERE WHAKARATO	28-QFN (4x5)
RAUPAPA	-
TUHINGA	-
PACKAGING	Tube
PAA / CASE	28-VFQFN Exposed Pad
TAE MAHI	-40°C ~ 85°C
TE MAHA O NGA KAIKOI / KAIWHIWHI	0/3
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
TE TAE KAITUKU TAEKE	6 Weeks
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
POROHITA	-
WHAKAAHUATANGA TAIPITOPITO	0/3 Receiver 28-QFN (4x5)
RARAUNGA RARAUNGA	-
TAU WAE TUAKIRI	ISL59910

Ngā tūtohu e hāngai ana

Intersil ISL59910IRZ	Kaitoha ISL59910IRZ	Kaiwhakarato ISL59910IRZ
Utu ISL59910IRZ	Pikitia ISL59910IRZ	Whakaahua ISL59910IRZ
ISL59910IRZ Pepa Raraunga PDF	ISL59910IRZ Tango Whakahoki	Tapunga ISL59910IRZ
Hokona ISL59910IRZ	Hokona ISL59910IRZ	Hokona Intersil ISL59910IRZ
Intersil ISL59910IRZ	Kaiwhakarato Intersil	Kaitoha Kaatawhai Intersil
Intersil ISL59910IRZ		

Ngā Hua e hāngai ana

 <p>ISL59910IRZ-T7 Kaihanga: Intersil Whakaahuatanga: IC RCVR/EQUALZR TRPL DIFF 28QFN I roto i te taonga: 723 pcs</p> <p>RFQ</p>	 <p>ISL59913IRZ Kaihanga: Intersil Whakaahuatanga: IC RCVR/EQUALZR TRPL DIFF 28-QFN I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>ISL59886ISZ Kaihanga: Intersil Whakaahuatanga: IC SEPARATOR VID SYNC AUTO 8SOIC I roto i te taonga: 183 pcs</p> <p>RFQ</p>	 <p>ISL59885ISZ Kaihanga: Intersil Whakaahuatanga: IC SEPARATOR VID SYNC AUTO 8SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>ISL59885ISZ-EVAL Kaihanga: Intersil Whakaahuatanga: EVAL BOARD FOR ISL59885 I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>ISL59911IRZ Kaihanga: Intersil Whakaahuatanga: IC RCVR/EQUALZR TRPL DIFF 32QFN I roto i te taonga: 584 pcs</p> <p>RFQ</p>
 <p>ISL59911IRZ-T7 Kaihanga: Intersil Whakaahuatanga: IC RCVR/EQUALZR TRPL DIFF 32QFN I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>ISL59885ISZ-T7A Kaihanga: Intersil Whakaahuatanga: IC SYNC SEPARATOR HD/SD 8SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>ISL59885ISZ-T7 Kaihanga: Intersil Whakaahuatanga: IC VIDEO SYNC SEPARATOR 8-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>ISL59885ISZ-T13 Kaihanga: Intersil Whakaahuatanga: IC SYNC SEPARATOR HD/SD 8-SOIC I roto i te taonga: Out stock</p> <p>RFQ</p>
 <p>ISL59910IRZ-EVALZ Kaihanga: Intersil Whakaahuatanga: EVAL BOARD FOR ISL59911IRZ I roto i te taonga: Out stock</p> <p>RFQ</p>	 <p>ISL59911IRZ-EVALZ Kaihanga: Intersil Whakaahuatanga: EVALUATION BOARD FOR ISL59911 I roto i te taonga: Out stock</p> <p>RFQ</p>