



Leader Tech Inc.

59-CBSA-3.0X3.75X0.5

Tau Wae: 59-CBSA-3.0X3.75X0.5
 Kaihanga / Waitohu: Leader Tech Inc.
 Whakaahuatanga hua: 59 SERIES CBS SHIELD ASSEMBLY -
 Ngā Rauemi: [1.59-CBSA-3.0X3.75X0.5.pdf](#)
[2.59-CBSA-3.0X3.75X0.5.pdf](#)
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 59-CBSA-3.0X3.75X0.5

TAU WAE	59-CBSA-3.0X3.75X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	59 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
PEPA RARAUNGA	1.59-CBSA-3.0X3.75X0.5.pdf 2.59-CBSA-3.0X3.75X0.5.pdf
WHĀNUI - WHĀNUI	3.000" (76.20mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	59-CBSA-3.0X3.75X0.4 59-CBSA-3.0X3.75X0.4-ND
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE TAE KAITUKU TAEKE	2 Weeks
TE ROA - WHĀNUI	3.750" (95.25mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 3.000" (76.20mm) X 3.750" (95.25mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 59-CBSA-3.0X3.75X0.5	Kaitoha 59-CBSA-3.0X3.75X0.5	Kaiwhakarato 59-CBSA-3.0X3.75X0.5
Utu 59-CBSA-3.0X3.75X0.5	Pikitia 59-CBSA-3.0X3.75X0.5	Whakaahua 59-CBSA-3.0X3.75X0.5
59-CBSA-3.0X3.75X0.5 Pepa Raraunga PDF	59-CBSA-3.0X3.75X0.5 Tango Whakahoki	Tapunga 59-CBSA-3.0X3.75X0.5
Hokona 59-CBSA-3.0X3.75X0.5	Hokona 59-CBSA-3.0X3.75X0.5	Hokona Leader Tech Inc. 59-CBSA-3.0X3.75X0.5
Leader Tech Inc. 59-CBSA-3.0X3.75X0.5	Kaiwhakarato Leader Tech Inc.	Kaitoha Kaatawhai Leader Tech Inc.
Leader Tech Inc. 59-CBSA-3.0X3.75X0.5		

Ngā Hua e hāngai ana

 59-CBSA-3.0X4.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ	 59-CBSA-3.0X3.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ
 59-CBSA-3.0X3.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ	 59-CBSA-3.0X4.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ
 59-CBSA-2.75X6.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ	 59-CBSA-3.0X3.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ
 59-CBSA-3.0X5.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ	 59-CBSA-2.75X5.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ
 59-CBSA-3.0X4.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ	 59-CBSA-2.75X5.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ
 59-CBSA-3.0X4.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ	 59-CBSA-3.0X5.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: Out stock RFQ

