



SICK

## DGS35-1K405000

Tau Wae:	DGS35-1K405000
Kaihanga / Waitohu:	SICK
Whakaahuatanga hua	ROTARY ENCODR INCREMENT 5000PPR
Ngā Rauemi:	
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS


[TONO MO TE WHAKAHUA](#)

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













## Ngā whakaaturanga o DGS35-1K405000

TAU WAE	DGS35-1K405000
KAIHANGA	SICK
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 5000PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
PEPA RARAUNGA	
TUHINGA O MUA	4.5 V ~ 5.5 V
KĀHUA WHAKAMUTUNGA	Connector
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	5000
MOMO PUTANGA	-
ĒTAHI INGOA	1061762
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
TE TAE KAITUKU TAEKE	3 Weeks
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

## Ngā tūtohu e hāngai ana

SICK DGS35-1K405000	Kaitoha DGS35-1K405000	Kaiwhakarato DGS35-1K405000
Utu DGS35-1K405000	Pikitia DGS35-1K405000	Whakaahua DGS35-1K405000
DGS35-1K405000 Pepa Raraunga PDF	DGS35-1K405000 Tango Whakahoki	Tapunga DGS35-1K405000
Hokona DGS35-1K405000	Hokona DGS35-1K405000	Hokona SICK DGS35-1K405000
SICK DGS35-1K405000	Kaiwhakarato SICK	Kaitoha Kaatawhai SICK
SICK DGS35-1K405000		

## Ngā Hua e hāngai ana

 <p><b>DGS35-1K200120</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENTAL 120PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1KK02048</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1HN02048</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1HN04096</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1JK04096</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1J405000</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1L202048</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1J202048</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1KN02048</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1KK05000</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1KK02500</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1KK01024</b> Kaihanga: SICK Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: Out stock</p> <p><a href="#">RFQ</a></p>